TO G.W Howard | AT Sfield / Sales

SUBJECT Ford Parts & Service RFQ-SmR-87-29 | DATE 1-27-87

There is no additional cost and therefore no price change to FP&S for obsolescence of 41516 label and introduction of label no 1190.

I realize that due to the extreme time lapse FP&S has already made this assumption. FP&S RFQ's are returned to you in case you need them.

DUPLICATE SIGNED Karen Schuessler ext 541

DATE | SIGNED

REDIFORM 4S 469
POLY PAK (50 SETS) 4P 469

SEND PARTS 1 AND 3 INTACT -
PART 3 WILL BE RETURNED WITH REPLY.

carbonless

DETACH AND FILE FOR FOLLOW-UP

Marketing Request

Bendix

Bendix Friction Materials Division
Southfield MI 48086

Allied Signal

SOUTHFIELD TRACK # SMR-87- 29 MARKETING REQUEST # NO MR - SEE memo attd

Reference BOTH numbers above for tracking purposes, thank you. 1-27-88

DATE: 7-7-87
TO MARKETING: K.E. Schwilling
FROM SALES: G.W. Howard
CUSTOMER: FPSD
CUSTOMER RFQ #: 7-2-87
REQUESTED RESPONSE DATE: 7-16-87

FAX ☐ AIR ☒ MAIL ☐

ATTACHMENTS?: prints ☐ other ☒

MODEL YEAR: All with active Service parts
VEHICLE OR PROGRAM: All current, brake lining Service Kits & containing Asbestos

CUSTOMER PART NUMBER	FORMULA	SIZE OF PART	TYPE OF PART	VOLUME
See attached List				All current orders w/ Asbestos.

DIFFERENCE IF SIMILAR TO CURRENT PROGRAM: Kit being revised for change in packaging ie. New Asbestos WARNING label.

COMPETITIVE INFORMATION AND GENERAL COMMENTS:

ACTION REQUIRED: Please advise piece price, tooling (IF ANY) & timing to make indicated change. Also provide packaging costs separately.

SALES MANAGER APPROVAL: [signature] DATE: 7-8-87

cc: File

022787

HWCPI0000369