

Industrial Hygiene Audit/Tour on 7/29/91

- 1) Electrical/Capital Planning Warehouse
 - A) Contractor Lunchroom
 - B) Electrician Shop Area
- 2) Welding Shop
 - A) Carpenter' Area → *warning Protection sign*
 - B) Welding Area
- 3) Material Warehouse
 - A) SCBA Full Face Masks → *egress system for breathing air system*
 - B) PPE
 - C) Asbestos Gasket Storage
 - D) Respirator Cleaning Station
 - E) Contractor Lunchroom
 - F) Restroom
 - G) EDO Shop
 - H) Solvent Cleaning Area → *warning sign on varsol tank*
 - I) EDO Lunchroom
 - J) Texas Nuclear in Cell Crew Lab
- 4) Signs to enter Cell Area
- 5) C-701A (high noise area)
- 6) Dielectric Boot Test Shack
- 7) Control Building
 - A) Cell operator's Lab
 - B) SCBA Breathing Air Containers
 - C) Lunchroom
 - 1) Bulletin Board
 - 2) Radiation Certificate of Responsibility
 - D) Safety SOS Office
 - 1) C-9 Records
 - 2) OSHA STAR records
 - E) Control Room
 - 1) Breathing Air Mask location
 - 2) Breathing Air lines

- Need collection point for liquid chlorine
- Need collection point @ Taffy Pot.
→ Are the Scott Ovisia's up to date
- 8) Cell Sewer Sump
 - A) Asbestos Cleaning Station
 - B) Asbestos Disposal Dumpster

> check if covered under RADIF. Do we have a job procedure.
- 9) T-56 (level OHMART)
- 10) C-90/C-91 Area (high noise)
- 11) C-100A Area (high noise)
- 12) P-260 Area (high noise)
- 13) Control Room Breathing Air Container Storage
- 14) Brine Treating Lab
- 15) Front Office
 - A) Chemical Laboratory
 - B) Murphy's Office *Etho Can*
 - C) Changehouse
 - D) Copier Room
 - 1) Safety Files
 - 2) Bulletin Board

7/26/91 ---->kgj

DO A 043261
CONFIDENTIAL