TECH

Mr. S. F. Teague, Jr.
Mr. P. G. Benignus
Mr. John B. Trotter
Mr. H. L. Welsted

December 16, 1952

Industrial Chemical Company
Lenoir
North Carolina.

Mr. E. C. Miller

Dear Ed:-

Your problem with regard to removing AROCLOR 1254 (Chlorinated Biphenyl) from the drums in cold weather has been carefully reviewed with our Technical Department.

They tell me that a common practice for removing such materials is to insert a sabre type electric immersion type heater through the bung of such drums. They believe that you will find this of help in emptying the Aroclor 1254 from the drums during the cold weather.

If we can give you further help in this connection, please let me know.

Very best wishes.

Sincerely yours,

Howard A. Lovejoy
Assistant Branch Manager

sg

II 34

DSW 550810

STLCOPCB4089227