Ford

APR 16 3 53 PM '79
INDUSTRIAL RELATIONS
Personnel and Organization Staff

Inter Office

April 17, 1979

PLAINTIFF'S EXHIBIT
FD-51b

To: J. J. Whelan

cc: A. W. Hanlon
N. A. Lessig

Subject: Asbestos Usage in the Rouge Operations

With regard to asbestos usage in the Rouge operations, we have made an audit accompanied by Don Reardon, Unit Health and Safety Representative, of plant locations where he or people he represents have identified asbestos usage. For the most part, the products seem to be asbestos tape used by electricians to wrap high voltage transmission lines. We did uncover "asbestos board" at some locations. However, samples are being analyzed to assure that these are indeed made from asbestos. There still remains pipe covering composed mainly of asbestos that can still be found at older locations. However, replacement covers are non-asbestos materials.

An alleged "asbestos" insulation packing used around coke oven doors was found to be a non-asbestos product.

We are attempting to determine the need for using asbestos tape in electrical operations and will try to convince maintenance personnel that substitutes could probably be as effective.

Paul E. Toth, Manager
Industrial Hygiene and
Toxicology Department

kb

8008 0099

PQ

PRODUCED BY FORD

Sherman + Reinhardt Laurie

Thea Mengele audit - ① found none of these items
(showing removed)

② Sandwelding - electrical cable (heavy duty)
When splicing cable - wrap with
asbestos tape.
This continues.
Recommendations not to use. (substitutes
available)

③ Cache of materials in storage (elect tape)
for use in B Formale area -
to wrap pipes - sludge lines.

④ Again recommended substitutes (to N. N. Smith

⑤ 1957 - asbestos tape for cable -
Shielding materials were not asbestos. (Cancelled
Not signed)

⑥ 1957 - asbestos tape -
shielding boxes (4x4x4 about 8 in dia,
cut with saw.
Recommendations to steel Mercury
(Arrow Memorial Letter.)

Smiley, Regent and Steel removed in steel Mercury storage.

⑦ Need sealed cable area doors - no asbestos -
Cancelled Not signed.

PQ
8008 0100

PRODUCED BY FORD