FRICTION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468

A U T O M O T I V E D A T A B O O K B U L L E T I N #1-921

October 9, 1992

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
ACURA				
1993, Integra		7445-D409**	D/D	7443-D564**
1993, NSX		7382-D503**	D/D	7383-D504**
BUICK				
1993, Riviera		7384-D505**	D/D	7387-D508**
1993, Roadmaster		7214A-D52	D/BH	2134BTT-S652
1993, Skylark		7385-D506**	D/BH	2164-553
CADILLAC				
1993, DeVille		7384-D505**	D/N	1394-S636
1993, Eldorado		7384-D505**	D/D	7387-D508**
1993, Limousine		7259-D369**	D/BH	2134BTT-S652
1993, Seville		7384-D505**	D/D	7387-D508**
CHEVROLET				
1993, Caprice		7214A-D52	D/BH	2117BTT-S650
	OR		/BH	2134BTT-S652
1993, Caprice Wagon		7214A-D52	D/BH	2134BTT-S652
1993, Cavalier		7385-D506**	D/BH	2164-553
1993, Lumina APV		7384-D505**	D/N	1394-S636
EATON				
Front Axle				
15 x 4 ES		1443TT-S664 (Note #25)	A/	
FORD				
1993, Festiva		7291-D402**	D/N	1406-595
1993, Mustang 2.3L		7072B-D237	D/BH	2151T-569*
1993, Mustang GT 5.0L		7379A-D421	D/BH	2151T-569*
1993, Probe		7463-D583** (Notes #9 & 22)	D/N	1407-S667* (Note #28)
	OR		/D	7464-D584** (Notes #10 & 23)
1993, Tempo		7411A-D257	D/N	1350-501*
1993, Thunderbird		7304A-D417	D/N	1396-S618
1993, Thunderbird Super Coupe		7304A-D417	D/D	7239A-D545
FORD TRUCK				
1993, Bronco		7361-D375**	D/BH	2141AT-582
1993, Explorer		7125A-D387	D/BH	2089AT-581
1993, E-150		7361-D375**	D/BH	2141AT-582
1993, E-250		7436-D557**	D/BH	2146T-316
	OR		/BH	2140AT-314
1993, E-350		7436-D557**	D/BH	2140AT-314
	OR		/BH	2171T-583*

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
FORD TRUCK (con't)				
1993, F-150		7361-D375**	D/BH	2141AT-582
1993, F-250		7330-D450**	D/BH	2146T-316
	OR		/BH	2140AT-314
1993, F-350		7330-D450**	D/BH	2140AT-314
	OR		/BH	2171T-583*
1993, F-450 Chassis		7299-D411**	D/D	7299-D411**
1993, Ranger		7125A-D387	D/BH	2151T-569
	OR		/BH	2089AT-581
HONDA (See Corrections)				
1993, Civic Delsol		7439-D560**	D/N	1379-S639*
	OR		/D	7443-D564**
1993, Civic 4Dr (Exc. EX)		7439-D560**	D/N	1379-S639*
	OR		/N	1364-576*
1993, Civic 4Dr EX		7445-D409**	D/D	7443-D564**
1993, Prelude (Exc. SR)		7448-D568**	D/D	7418-D537**
1989-88, Civic CRX Si		7178-D273**	D/N	1379-546*
1987-86, Civic CRX Si		7162-D256**	D/N	1379-546*
ISUZU				
1992, Trooper		7459-D579** (Notes #5 & 18)	D/D	7460-D580** (Notes #6 & 19)
MAZDA				
1993, Miata		7337-D525**	D/D	7338-D458**
1993, MX3		7353-D473**	D/N	8104-S659*
	OR		/D	7453-D573**
1993, MX6		7463-D583**	D/N	1407-S667*
	OR		/D	7464-D584**
1993, RX7		7465-D585** (Notes #11 & 24)	D/D	7186-D482**
1993, Navajo		7125A-D387	D/BH	2089AT-581
1993, Protege		7219-D466**	D/N	8104-S659*
	OR	7353-D473**	D/D	7338-D458**
1993, 323		7219-D466**	D/N	8104-S659*
1993, 626		7463-D583**	D/N	1407-S667*
	OR		/D	7464-D584**
1993, 929		7431-D552**	D/D	7432-D553**
1993, MPV 2WD		7429-D550**	D/BH	2172-609*
1993, MPV 4WD		7430-D551**	D/BH	2172-609*
1993, B2200		7454-D574**	D/N	1344-565*
1993, B2600 2WD		7454-D574**	D/N	1344-565*
1993, B2600 4WD		7220-D320**	D/BH	2172-S626*
MERCEDES				
1992-91, 300 SD		7458-D578** (Notes #4 & 17)	D/D	7374-D495**
1992-91, 300 SE		7458-D578**	D/D	7374-D495**
1992-91, 400 SE		7457-D577** (Notes #3 & 16)	D/D	7374-D495**
1992-91, 500 SEL		7457-D577**	D/D	7374-D495**
1992-91, 600 SEL		7457-D577**	D/D	7374-D495**
MERCURY				
1993, Capri		7240-D348**	D/D	7257-D366**
1993, Topaz		7411A-D257	D/N	1350-501*
1993, Villager		7456-D576** (Notes #2 & 15)	D/N	1452-S665 (Notes #12 & 26)

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
MITSUBISHI				
1993, 3000 GT		7412-D530**	D/D	7272-D383**
1993, 3000 GT VR4		7413-D531**	D/D	7414-D532**
1993, Diamante		7412-D530**	D/D	7272-D383**
1993, Eclipse		7365-D484**	D/D	7415-D533**
1993, Eclipse 4WD		7412-D530**	D/D	7415-D533**
1993, Galant		7365-D484**	D/N	1415-610*
	OR	7412-D530**	D/D	7415-D533**
NISSAN				
1993, Quest		7456-D576**	D/N	1452-S665
OLDSMOBILE				
1993, Achieva		7385-D506**	D/BH	2164-553
1993, Cutlass Ciera		7136-D215**	D/N	1394-S636
1993, Silhouette APV		7384-D505**	D/N	1394-S636
PONTIAC				
1993, Grand Am		7385-D506**	D/BH	2164-553
1993, Sunbird		7385-D506**	D/BH	2164-553
1993, Transport		7384-D505**	D/N	1394-S636
ROCKWELL				
Disc Brakes	ADB 1760	7455-D575** (Notes #1 & 14)	D/D	7455-D575**
	ADB 1540	7172-D267**	D/	
	ADB 1560	7173-D268**	D/D	7173-D268**
SUZUKI				
1992, Sidekick 2DR		7305-D418**	D/N	1440-S641*
1992, Swift		7331-D451**	D/N	1414-608*
1992, Swift GT/GTI		7332-D452**	D/D	7180-D277**
TOYOTA				
1993, MR2 Turbo		7462-D582** (Notes #8 & 21)	D/	
VOLKSWAGEN				
1993, Eurovan		7461-D581** (Notes #7 & 20)	D/N	1453-S666* (Notes #13 & 27)
1993-92, Fox (Exc. Wagon)		7242-D350**	D/N	1354-559
1993-92, Fox Wagon		7242-D350**	D/N	1402-495
1993, Passat		7143-D227**	D/D	7234-D340**
	OR	7177-D227**	D/	

C O M M E N T S

Existing lining used with new shoe:

Lining	Assembly	Application
1443TT	1443TT-S664	Eaton Front Axle 15 x 4 ES
1407	1407-S667	1993 Ford Probe Rear
		1993 Mazda MX6 Rear
		1993 Mazda 626 Rear

C O R R E C T I O N S

Honda - Catalog lists 7162-D256 for front of Honda Civic CRX Si 1989-86. Correct front brakes are 1989-88, 7178-D273 and 1987-86, 7162-D256.

DISC BRAKE LINING ASSIGNMENTS

Note #1	FMSI 7455 59.0 x 30.4 x 294 63.5 x 20.9 x 294 (2.32 x 1.197 x 11.58) (2.50 x .823 x 11.58)	7455-D575 2 IM 2
Note #2	FMSI 7456 45.3 x 15.8 x 144.3 45.3 x 15.8 x 144.3 (1.78 x .622 x 5.68) (1.78 x .622 x 5.68)	7456-D576 2 IM 2
Note #3	FMSI 7457 67.1 x 17.8 x 96.3 (2.64 x .701 x 3.79)	7457-D577 4 IM
Note #4	FMSI 7458 62.0 x 17.4 x 86.4 (2.44 x .685 x 3.40)	7458-D578 4 IM
Note #5	FMSI 7459 47.5 x 16.5 x 122.7 (1.87 x .650 x 4.83)	7459-D579 4 IM
Note #6	FMSI 7460 37.3 x 15.8 x 94.5 (1.47 x .622 x 3.72)	7460-D580 4 IM
Note #7	FMSI 7461 53.8 x 17.9 x 87.1 (2.12 x .705 x 3.43)	7461-D581 4 IM
Note #8	FMSI 7462 48.5 x 15.6 x 117.3 (1.91 x .614 x 4.62)	7462-D582 4 IM
Note #9	FMSI 7463 42.7 x 16.1 x 117.9 42.7 x 15.0 x 117.9 (1.68 x .634 x 4.64) (1.68 x .591 x 4.64)	7463-D583 2 IM 2
Note #10	FMSI 7464 35.0 x 13.6 x 89.9 (1.38 x .535 x 3.54)	7464-D584 4 IM
Note #11	FMSI 7465 49.3 x 14.8 x 105.2 49.3 x 14.8 x 105.2 (1.94 x .582 x 4.14) (1.94 x .582 x 4.14)	7465-D585 2 IM 2

DRUM BRAKE LINING ASSIGNMENTS

Note #12

FMSI 1452
250.0dd - 55.2 x 6.3 x 248.7
(9.84 - 2.17 x .248 x 9.79)

1452-S665
4 - 40

Note #13

FMSI 1453
270.0dd - 55.0 x 5.8 x 226.0
270.0 - 55.0 x 5.8 x 279.4
(10.63 - 2.17 x .228 x 8.90)
(10.63 - 2.17 x .228 x 11.00)

1453-S666
2 Bonded
2

DISC BRAKE SHOE ASSIGNMENTS

Note #14

FMS D575
296.0 x 7.9
296.0 x 6.4
(11.65 x .311)
(11.65 x .250)

7455-D575

Rockwell
Axle

Note #15

FMS D576
188.0 x 5.9
188.0 x 5.9
(7.40 x .232)
(7.40 x .232)

7456-D576

Mercury
Nissan

Note #16

FMS D577
97.8 x 4.6
(3.85 x .181)

7457-D577

Mercedes

Note #17

FMS D578
87.9 x 4.6
(3.46 x .181)

7458-D578

Mercedes

Note #18

FMS D579
137.7 x 6.0
(5.42 x .236)

7459-D579

Isuzu

Note #19

FMS D580
109.7 x 7.0
(4.32 x .276)

7460-D580

Isuzu

Note #20

FMS D581
91.4 x 5.1
(3.60 x .201)

7461-D581

Volkswagen

Note #21

FMS D582
141.0 x 5.6
(5.55 x .220)

7462-D582

Toyota

Note #22

FMS D583
131.6 x 6.1
131.6 x 5.1
(5.18 x .240)
(5.18 x .201)

7463-D583

Ford
Mazda

Note #23

FMS D584
100.1 x 5.7
(3.94 x .224)

7464-D584

Ford
Mazda

DISC BRAKE SHOE ASSIGNMENTS (Con't)

Note #24	FMS D585 106.9 x 5.6 106.9 x 4.6 (4.21 x .220) (4.21 x .181)	7465-D585	Mazda

DRUM BRAKE SHOE ASSIGNMENTS

Note #25	FMS S664 15.00 x 4.00	1443TT-S664	Eaton
Note #26	FMS S665 250.0 x 55.0 (9.84 x 2.17)	1452-S665	Mercury Nissan
Note #27	FMS S666 270.0dd x 55.0 (10.63 x 2.17)	1453-S666	Volkswagen
Note #28	FMS S667 228.6dd x 30.0 (9.00 x 1.18)	1407-S667	Ford Mazda

CLUTCH FACING APPLICATIONS BY MODEL

TOYOTA	
1977-71, Celica	8036A (Note #29)
1974-71, Corona	8036A
1976-72, Corona MK III	8036A
1980-81, 4 Runner	8036A
1980-71, Pickup	8036A

CLUTCH FACING ASSIGNMENTS

Note #29	FMSI 8036A 8.86 x 6.30 x .137	16 Gr A Str - 16	

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.