

Please be specific when filling out the dosimetry cards in regards to respirator use, possible overexposure events, and job activity (for vinyl operators this includes telling what area of vinyl you worked in: New Unit, Old Unit, SA Module, or Dryers; for Mx list the jobs worked and where). Also list every time a VCM line is "broken" (e.g. cleaned dump strainer, compressor work, unhooked # railcars, etc...). The more information you provide, the more capable we will be to determine the source of overexposure and possibly improve conditions. Thank you, Shea