Monsanto

File - PCB Misc.

JUN 24 1980

FROM (NAME—LOCATION—PHONE) J. H. Craddock - St. Louis CS1H 4-4764

DATE : June 20, 1980

cc: C. F. Callis - B2SA
R. S. Nelson - CS1H
J. R. G. Ortiz - E2ND
George Roush, Jr. - A2SA

SUBJECT :

REFERENCE :

TO : P. E. Berteau - A2SC

Regarding the request for information from Dr. Hallet Lewis on Askarel material supplied to Niagara Transformer Corp., I talked to Mr. Gabel, General Manager of Niagara Transformer Corp., and identified the Askarel material as Inerteen 70/30.*

Attached is a copy of the Material Safety Data Sheet for this material. All that Dr. Lewis requested of Niagara Transformer Corp. and of Dr. Roush in his letter was a copy of the Material Safety Data Sheet.

The Niagara Transformer Corp. also supplied Dr. Lewis with a copy of their Precautionary Procedure IEEE guide for maintenance of Askarel equipment. The information in our product bulletin is very similar to these documents.

Please consider whether we need to respond with more than the Material Safety Data Sheet requested by Dr. Lewis. Let me know your thoughts before mailing your response.

*70% Aroclor 1254, 30% Trichlorobenzene

J. H. Craddock

jb
enclosures