

C O P Y

Buick Returns 3388 - 3855

March 5, 1968

D. R. Tarne

cc: H. H. Dalziel
W. J. Sheehan ✓
C. M. Nielsen
G. H. Brown
C. W. Watrous

The quantity of parts as indicated at the end of this note is the result of discussions held with Buick Sales and Engineering personnel.

Mr. Roy Bates and the writer requested of Mr. Dalziel to negotiate a settlement with Buick, based on the fact, that the Victor parts were to print requirements.

Mr. H. H. Dalziel has informed the writer that Buick has refused to pay for any of the parts in question, due to the problems they encountered in sealing the engines with these parts. Mr Dalziel further indicated that these parts could be used for service requirements and for our jobber. Our jobber sales for 3388-B8 were 400 pieces in 1967. No sales on 3855 for 1967.

Since we do not have any service requirements what disposition shall be made of these parts.

3388-BSM - 63,291 pcs. - Manufacturing cost \$158.25/M

3855-BSM - 22,590 pcs. - Manufacturing cost \$141.24/M

These parts are being held in Receiving Inspection.

L. S. Dymitro

LSD:rb

*Turn to review
for review
sent
3-7-68*

VPD-91-0001438

DANA-150