FRICTION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468

A U T O M O T I V E D A T A B O O K B U L L E T I N #3-931

December 21, 1993

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
AUDI				
1994, 90		7352-D419**	D/D	7309-D228**
1994, 90 Quattro		7352-D419**	D/D	7309-D228**
1994, 100		7434-D555**	D/D	7309-D228**
1994, 100 Quattro		7434-D555**	D/D	7309-D228**
1994, S4		7306-D419**	D/D	7309-D228**
1993, S4		7306-D419**	D/D	7309-D228**
	OR	7434-D555**	D/	
1994, V8 Quattro		7306-D419**	D/D	7309-D228**
	OR	7346-D467**	D/	
BUICK				
1994, Century		7136-D215**	D/N	1394-S636
1994, LeSabre		7384-D623**	D/N	1394-S636
1994, Park Avenue		7384-D623**	D/N	1394-S636
1994, Regal		7265-D376**	D/D	7387-D508**
1994, Roadmaster		7214A-D52	D/BH	2134BTT-S652
1994, Skylark		7385-D506**	D/BH	2164-553
CHEVROLET (See Comments)				
1994, Beretta		7385-D506**	D/BH	2164-553
1994, Camaro		7384-D623**	D/BH	2117BTT-S651
	OR		/D	7301-D413**
1994, Caprice		7214A-D52	D/BH	2117BTT-S650
	OR		/BH	2134BTT-S652
1994, Caprice Wagon		7214A-D52	D/BH	2134BTT-S652
1994, Caprice Police		7506-D614** (Note #5)	D/D	7505-D628** (Notes #4 & #16)
1994, Cavalier		7385-D506**	D/BH	2164-553
1994, Corsica		7385-D506**	D/BH	2164-553
1994, Corvette		7300-D412**	D/D	7301-D413**
1994, Lumina		7265-D376**	D/D	7266-D377**
1994, Lumina Minivan		7384-D623**	D/N	1394-S636
CHRYSLER (See Comments)				
1994, Concorde		7470A-D591	D/D	7438A-D559
1994, LeBaron Convertible		7403A-D521	D/N	1444-S657*
	OR	7404A-D522	D/D	7438A-D559
1994, Town & Country		7406-D524**	D/BH	2176T-538 (Note #12)
	OR	7404A-D522	D/	
DODGE/PLYMOUTH				
1994, Colt 2DR		7482-D602**	D/N	1442-S644*
1994, Colt 4DR		7483-D602**	D/N	1415-S677*
	OR		/D	7474-D596**
1994, Colt Vista		7365-D484**	D/N	1415-S677*
	OR		/D	7272-D383**
1994, Colt Vista 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.
Copyright© by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
DODGE (See Comments)				
1994, Intrepid		7470A-D591	D/N	1456-S657*
	OR		/D	7438A-D559
1994, Shadow		7403A-D521	D/N	1365-519
1994, Stealth		7412-D530**	D/D	7272-D383**
1994, Stealth 4WD		7413-D531**	D/D	7414-D532**
1994, Viper		7471-D592**	D/D	7472-D491**
1994, Caravan		7406-D524**	D/BH	2176T-538
	OR	7404A-D522	D/	
1994, Grand Caravan		7406-D524**	D/BH	2176T-538
	OR	7404A-D522	D/	
DODGE TRUCK (See Comments)				
B150 1994		7179A-D269	D/BH	2025T-446*
B250 1994		7179A-D269	D/BH	2025T-446*
B350 1994		7179A-D269	D/BH	2146AT-357
	OR		/BH	2140AT-358
1994, Caravan C/V		7406-D524**	D/BH	2176T-538
	OR	7404A-D522	D/	
1994, Dakota		7410A-D593	D/BH	2176T-538
	OR	7410A-D593	D/BH	2089T-445**
EAGLE				
1994, Summit 2DR		7482-D602**	D/N	1442-S644*
1994, Summit 4DR		7483-D602**	D/N	1415-S677
	OR		/D	7474-D596**
1994, Summit Wagon		7365-D484**	D/N	1415-S677**
	OR		/D	7272-D383**
1994, Summit Wagon 4WD		7365-D484**	D/N	1445-S658*
			/D	7272-D383**
1994, Vision		7470A-D591	D/D	7438A-D559
FORD				
1994, Mustang			/D	7504-D627** (Notes #3 & #15)
FORD TRUCK				
1994, Bronco		7503-D626** (Notes #2 & #14)	D/	
1994, E150		7503-D626**	D/	
1994, F150		7503-D626**	D/	
GEO				
1994-93, Prism		7441-D562**	D/N	8105-597*
JEEP (See Comments & Corrections)				
1993, Grand Cherokee		7507A-D477 (Note #6)	D/BH	2174TT-S670*
1994, Grand Cherokee		7507A-D477	D/BH	2174TT-S670*
	OR		/D	7502A-D625 (Notes #1 & 13)
1994, Cherokee		7507A-D477	D/BH	2176T-538
	OR		/BH	2174TT-S670*
1994, Wrangler		7358A-D477	D/BH	2176T-538
LEXUS				
1994, GS300		7495-D619**	D/D	7452-D572**
1994, SC300		7357-D476**	D/D	7452-D572**
1994, SC400		7451-D571**	D/D	7452-D572**

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
LINCOLN				
1994, Mark VIII		7476-D598**	D/D	7477A-D599
MITSUBISHI				
1994, 3000GT		7412-D530**	D/D	7272-D383**
1994, Diamante		7412-D530**	D/D	7272-D383**
1994, Expo		7365-D484**	D/N	1415-S677*
	OR		/D	7272-D383**
1994, Expo 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1994, Expo LRV		7365-D484**	D/N	1415-S677*
	OR		/D	7272-D383**
1994, Expo LRV 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1994, Mirage 2DR		7482-D602**	D/N	1442-S644*
1994, Mirage 4DR		7483-D602**	D/N	1415-S677*
	OR		/D	7474-D596**
1994, Pick Up		7241-D349**	D/N	1370-524*
OLDSMOBILE				
1994, Cutlass Ciera		7136-D215**	D/N	1394-S636
1994, Cutlass Supreme		7265-D376**	D/D	7387-D508**
1994, Eighty Eight		7384-D623**	D/N	1394-S636
1994, Ninety Eight		7384-D623**	D/N	1394-S636
1994, Silhouette		7384-D623**	D/N	1394-S636
PLYMOUTH (See Comments)				
1994, Voyager		7406-D524**	D/BH	2176T-538
	OR	7404A-D522	D/	
1994, Grand Voyager		7406-D524**	D/BH	2176T-538
	OR	7404A-D522	D/	
PONTIAC				
1994, Bonneville		7384-D623**	D/N	1394-S636
1994, Firebird		7384-D623**	D/BH	2117BTT-S651
	OR		/D	7301-D413**
1994, Grand Prix		7265-D376**	D/D	7387-D508**
1994, Trans Sport		7384-D623**	D/N	1394-S636
SUBARU				
1994, Justy (12" Wheels)		7362-D480**	D/N	1363-591*
1994, Justy (13" Wheels)		7377-D498**	D/N	1363-591*
1994, Legacy		7350-D470**	D/D	7351-D471**
	OR	7442-D563**	D/	
1994, SVX		7433-D554**	D/D	7351-D471**
SUZUKI				
1994, Swift		7331-D451**	D/N	1414-608*
	OR		/N	1461-S630*
1994, Swift GT		7332-D452**	D/D	7180-D277**
1994, Sidekick 2DR		7305-D418**	D/N	1440-S641*
1994, Sidekick 4DR		7435-D556**	D/N	1446-S660*
TOYOTA				
1994, Corolla		7441-D562**	D/N	8105-597*
1994, Paseo		7153-D242**	D/N	1439-S642*
1994, Tercel		7153-D242**	D/N	1439-S642*
1994, T100 4WD		7298-D611**	D/N	1397-589*
1994, T100 1/2 Ton 2WD		7485-D604**	D/N	1397-589

			FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
TOYOTA (con't)					
1994, T100 1Ton			7486-D605**	D/N	1383-549*
1994-93, Supra Turbo			7508-D629**	D/D	7509-D630**
			(Notes #7 & #17)		(Notes #8 & #18)
UD (Nissan Commercial)					
CLA 83	1988-87		1411-603	N/N	1412-604
CMA-83	1988-87		1410-602	N/N	1434-S632
		OR		/N	1464-S679
					(Notes #9 & #19)
1100	1991-89		1465-S680	N/N	1465-S680
			(Notes #10 & #20)		
1300	1992		1466-S681	N/N	1466-S681
			(Notes #11 & #21)		
1800	1992-89		1410-602	N/	
2000	1992-89		1411-603	N/N	1412-604
2300	1991-90		1411-603	N/N	1412-604
2600	1992-89		1422-S617	N/N	1419-S614
2800	1992-89		1422-S617	N/N	1419-S614
3000	1991-89		1422-S617	N/N	1419-S614
3000 HD	1992		1422-S617	N/N	1419-S614
3000 SD	1992		1422-S617	N/N	1419-S614

C O M M E N T S

Existing shoe with new lining:

Shoe	Assembly	Application
D477	7507A-D477	1994-93 Jeep Grand Cherokee Front
		1994 Jeep Cherokee Front
D614	7506-D614	1994 Chevrolet Caprice Police Front
538	2176T-538	1994 Chrysler Town & Country Rear
		1994 Dodge Caravan & Grand Caravan Rear
		1994 Dodge Truck Caravan C/V & Dakota Rear
		1994 Plymouth Voyager & Grand Voyager Rear
		1994 Jeep Cherokee & Wrangler Rear

C O R R E C T I O N S

1993 Jeep Grand Cherokee is listed in catalog with FMSI 7358A-D477 front brakes. The correct listing is FMSI 7507A-D477.

DISC BRAKE LINING ASSIGNMENTS

Note #1	FMSI 7502A	7502A-D625
	30.5 x 10.0 x 124.8	4 - 24
	(1.20 x .394 x 4.91)	
Note #2	FMSI 7503	7503-D626
	49.8 x 16.0 x 150.0	2 IM
	49.8 x 16.0 x 150.0	2 IM
	(1.96 x .630 x 5.91)	
	(1.96 x .630 x 5.91)	
Note #3	FMSI 7504	7504-D627
	32.0 x 17.1 x 72.6	4 IM
	(1.26 x .673 x 2.86)	
Note #4	FMSI 7505	7505-D628
	38.1 x 14.6 x 122.4	4 IM
	(1.50 x .575 x 4.82)	

DISC BRAKE LINING ASSIGNMENTS (con't)

Note #5

FMSI 7506 — 7506-D614
48.3 x 17.4 x 171.2 — 2 IM
45.7 x 14.6 x 171.5 — 2 IM
(1.90 x .685 x 6.74)
(1.80 x .575 x 6.75)

Note #6

FMSI 7507A — 7507A-D477
43.0 x 11.3 x 157.8 — 4 - 28
(1.69 x .445 x 6.21)

Note #7

FMSI 7508 — 7508-D629
54.6 x 16.8 x 116.8 — 4 IM
(2.15 x .661 x 4.60)

Note #8

FMSI 7509 — 7509-D630
49.0 x 15.8 x 79.5 — 4 IM
(1.93 x .622 x 3.13)

DRUM BRAKE LINING ASSIGNMENTS

Note #9

FMSI 1464 — 1464-S679
320.0dd - 135.0 x 11.5 x 152.4 — 8 - 48
(12.60 - 5.31 x .453 x 6.00)

Note #10

FMSI 1465 — 1465-S680
320.0dd - 65.0 x 7.7 x 337.0 — 4 - 48
(12.60 - 2.56 x .303 x 13.27)

Note #11

FMSI 1466 — 1466-S681
320.0dd - 75.0 x 7.7 x 337.0 — 4 - 48
(12.60 - 2.95 x .303 x 13.27)

Note#12

FMSI 2176T — 2176T-538
230.0dd - 63.5 x 4.8 x 188.0 — 2 3mm 40
63.5 x 6.4 x 217.0 — 2
(9.00 - 2.50 x .188 x 7.40)
(2.50 x .250 x 8.55)

DISC BRAKE SHOE ASSIGNMENTS

Note #13

FMS D625 — 7502A-D625 — Jeep
140.2 x 5.1
(5.52 x .201)

Note #14

FMS D626 — 7503-D626 — Ford Truck
194.0 x 6.5
194.0 x 6.5
(7.64 x .256)
(7.64 x .256)

Note #15

FMS D627 — 7504-D627 — Ford
89.7 x 5.1
(3.53 x .201)

Note #16

FMS D628 — 7505-D628 — Chevrolet
135.9 x 6.0
(5.35 x .236)

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #17	FMS D629 119.4 x 5.1 (4.70 x .201)	7508-D629	Toyota
Note #18	FMS D630 80.8 x 5.1 (3.18 x .201)	7509-D630	Toyota

DRUM BRAKE SHOE ASSIGNMENTS

Note #19	FMS S679 320.0 x 135.0 (12.60 x 5.31)	1464-S679	UD
Note #20	FMS S680 320.0 x 65.0 (12.60 x 2.56)	1465-S680	UD
Note #21	FMS S681 320.0 x 75.0 (12.60 x 2.95)	1466-S681	UD

CLUTCH FACING APPLICATIONS BY MODEL

FORD TRUCK

Ford Truck	1283 (Note #22)
Ford Truck	1284 (Note #23)
Ford Truck	13000 (Note #24)

CLUTCH FACING ASSIGNMENTS

Note #22	FMSI 1283 12.79 x 7.91 x .138	40 DGAP	-	40
Note #23	FMSI 1284 12.75 x 7.53 x .170	40 DGAP	-	40
Note #24	FMSI 13000 13.80 x 8.35 x .170	40 DGAP	-	40

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.