COPY

VICTOPAC 60S
FOR JOHNSON MOTORS

AUGUST 16, 1968

H. NORTH

WE ARE VERTUALLY UNABLE TO SUPPLY VICTOPAC 60S TO THE CHICAGO PLANT IN ANY TYPE OF NORMAL FASHION. THE PROBLEM IS THAT THE MATERIAL STICKS IN TRANSIT AND IS REJECTED TO PLANT 4 FOR REPLACEMENT.

THIS CONDITION EXISTS AFTER THE FOLLOWING PRECAUTIONS HAVE BEEN TAKEN:

1. EXCESSIVE POWDERING
2. DELEAFING OF SHEETS TO INSURE NO STICKING IS TAKING PLACE.
3. SHIPPING WITH "DO NOT TOP" INSTRUCTIONS
4. ALLOWING TO THROUGHLY COOL BEFORE SHIPPING

WE ARE GOING TO START SHIPPING THE MATERIAL WITH LEAFING PAPER BETWEEN THE SHEETS. TO AVOID FURTHER PROBLEMS. YOU WILL BE ADVISED OF ADDITIONAL COSTS.

John Zeitz

JOHN ZEITZ

JZ/LC

CC: H. DEHR
C. MCNAMARA
J. QUENZER
V. SHEEHAN
R. WEEDON
L. WINCHESTER
FILE

VPD-91-0001132