John —

Highest value I've seen for dibenzofurans in aroclors is ~ 10ppm

So if residual [PCB] at a site was < 50ppm, then DF would be < 10 ppm of 50 ppm or < 500 ppt or less than COC guideline of 1 ppb.

I will have to call to find out what the Reported level was — the cap. had been hit by lightning & caught fire & there was no free oil left, So we never knew if the oil was contaminated or if the fire created the dibenzofurans —.
↑
probably the fire.

0673179
EX P-2292
Page 1 of 1
PCB-ARCH0745329