SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
See attached for vapors that can evolve during molding. Nuisance dust is 15 mg/m³.

EFFECTS OF OVEREXPOSURE
May cause skin irritation or dermatitis in sensitized individuals.

EMERGENCY AND FIRST AID PROCEDURES
Good personal hygiene. Avoid repeated or prolonged contact with skin — wash with soap and water at first opportunity. Flush eyes with water for at least 15 min.

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID: None known
	STABLE	X	

INCOMPATABILITY (Materials to avoid): None known

HAZARDOUS DECOMPOSITION PRODUCTS: Carbon dioxide, carbon monoxide, phenols, ammonia, formaldehyde.

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	None known

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Vacuum or sweep with sweeping compound to avoid generating dust.

WASTE DISPOSAL METHOD

1. Sanitary landfill recommended
2. Incineration

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type): Dust mask for nuisance dust

VENTILATION	LOCAL EXHAUST	X	SPECIAL	
	MECHANICAL (General)	X	OTHER	
PROTECTIVE GLOVES		X	EYE PROTECTION	X

OTHER PROTECTIVE EQUIPMENT: Dust collection system. Work areas to be in compliance with OSHA asbestos regulations.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Avoid exposure to temperature extremes and moisture — can affect product performance.

OTHER PRECAUTIONS: Avoid prolonged or repeated contact with skin. Avoid prolonged or repeated breathing of dust or vapors. Use with adequate ventilation.

GPO 934-110