

HOURLY SAFETY COMMITTEE  
MEETING  
JUNE 28, 1977

7/6/77  
Deckard  
May I please have  
answered by 7/15/77

PLAINTIFF'S EXHIBIT

MON-2949

|          |                 |         |                |
|----------|-----------------|---------|----------------|
| PRESENT: | Earl J. Hingle  | ABSENT: | R. S. Bessent  |
|          | Melvin Jackson  |         | Neal Jorgensen |
|          | Ryan G. Pittman |         | Arthur Mick    |
|          | A. N. Rich      |         | N. W. Preston  |
|          | M. L. Zeller    |         |                |

General:

This being the first meeting of the 1977 B-Term Hourly Safety Committee, the major objective was to be sure that they understood the plant safety program covered by Procedure Bulletin P-0100 and their respective functions in this program. The program was fully discussed covering all groups in the plant and their respective functions and questions about the program were answered.

OLD BUSINESS:

1. The program to sterilize and keep face shields which are used with portable grinders clean and sanitary is not working satisfactorily.

SC 12678

NEW BUSINESS:

1. At Dock 2 some type of cut-out "line pull" is needed on the small winch to prevent breaking cables and blocks when the boom is raised. These incidents have occurred several times in the past, and will continue to occur until some type load limit or cut-out device is used when raising the boom.
2. Telephone lines south of Department 19 control room in the pipe rack need to be retied to their original position. They are currently approximately two feet low and can be cut by crane booms.
3. We know that AN-5 has their own cyanide spill alarm, but it is not audible in all parts of the unit, but the main point is that many people do not know what the alarm is or what it sounds like. Suggest that it be revised to be heard in all parts of the unit and that Maintenance people be given an opportunity to hear the sound during their monthly safety meetings.

Deckard  
W/AN-5 people

LAM013873

4. Outside traffic and contractors' vehicles in the plant still creating serious problems in breaking speed limits, running stop signs, etc. Feels we have 50% too many vehicles in the plant.
5. Individual employees are not taking care of slings and the slings are being left in areas where they could become contaminated and made unsafe for future use. If a program is available on use and care of slings, it should be used at a monthly meeting for Maintenance personnel as a reminder of the importance of taking care of this equipment.
1. A serious problem exists in the Shops where employees wash parts in the kerosene and oil vat which becomes heavily contaminated with materials being washed from the parts. Is there is some type of more modern and safe vat which would eliminate employees putting their hands into this contaminated liquid?

*Decker  
W. Leonard  
Schwab*

*... also  
... solvent change when needed  
... are engineering into other methods that  
... available.*

SC

12679

LAM013874

NONNENMACHER

Week of 6/26/77

Discussed with utility department supervision proper procedure to be used for doing maintenance work on plant air drier 984A2-1 + 984A2-2. The silica gel loaded into vessel showed a slight reading on vapor tester.

Transported an injured construction worker to Danforth emergency room by plant ambulance.

Reported an exposed 110 volt wire at Dock #4 smoke pen to material handling supervision. This wire was repaired about a month ago and has shorted out again. Suggested a revision in this hookup.

Discussed with Dept. 13 and maintenance supervision proper method to be used in revision to 13S9 pit. Work was done under a special permit and completed without incident.

SC

12680

LAM013875