

VCM EXPOSURE TRAINING
TEST, 1981

55

4

Robert M. Nicholas

NAME

COMP

DEPARTMENT

2-19-81

DATE

1. The eight-hour exposure limit for VCM is 5 parts per million (average).
2. The 15-minute exposure limit for VCM is 1 parts per million (average).
3. You are required to wear an approved respirator in VCM concentrations above:
(a) 1.0 ppm b. 0.5 ppm c. 10.0 ppm d. 5.0 ppm
4. VCM is not a fire hazard. True False
5. Exposure to high levels of VCM over long periods of time may cause liver cancer and chromosome damage. True False
6. If you can't smell any VCM, you can be sure that there is not enough around to hurt you. True False
7. VCM is a colorless gas at normal temperature and pressure. True False OK
8. Breathing the smoke from burning VCM can cause severe lung damage or death. True False
9. Indicators of VCM leaks include "icing" and "hissing" sounds from processing equipment. True False
10. You must stay out of VCM regulated areas except when you have a reason to enter them because of your work. True False
11. Our Honeywell continuous monitors alarm when 1 ppm is detected in an area.
12. The VCM regulated areas in the plant are: (Circle a, b, c, or d)
 - a. The old reactor area and the VCM tank farm
 - b. The VCM compressor shed and the tops of the large slurry blend tanks.
 - c. ~~The two vinyl reactor areas, the tops of the large slurry blend tanks, the VCM compressor shed, and the tops of VCM tank cars.~~
 - d. The VCM storage sphere, the recovery areas in both vinyl units, the tops of VCM tank cars, and the east half of the plasticizer tank farm.
13. You must wear protective clothing when doing any job where your skin might come in contact with liquid VCM. True False
14. Any part of the body which is exposed to liquid VCM may be quickly and severely frostbitten. True False
15. When a VCM emergency begins, all plant workers not directly involved with handling the situation should immediately assemble in a group just north of the guardhouse. True False

TEST CONTINUED ON BACK

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger.

____ True

☒ False

17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations.

____ True

☒ False

18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations.

____ True

☒ False

19. Breathing high concentrations of VCM can cause you to pass out.

☒ True

____ False

20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible.

☒ True

____ False