Keyport file

SMITH MARINE SERVICE, INC.

3502 BROADWAY – P. O. BOX 12106
HOUSTON, TEXAS 77017
713/649-6083

October 14, 1974

Mr. Joe Sarne
Exxon Company, U.S.A.
P. O. Box 1512
Houston, Texas 77001

SUBJECT: Service Report

VESSEL: S.S. Exxon Boston; Newport News, Va.; 10-3-74 thru 10-6-74

1. Replaced selector switch, #2 burner, fire room console, starboard boiler.
2. Repaired selector switch, #1 burner, engine room console, port boiler.
3. Repaired alarm switch on de-superheater alarm, engineers panel. Assisted Copes-Vaulcan engineer on de-superheater controller. Replaced tube in controller (alarm unit).
4. Replaced #3 burner selector switch, starboard boiler, engine room console.
5. Replaced #1 burner ready relay, starboard boiler.
6. Replaced #2 burner ready relay, starboard boiler.
7. Adjusted main fuel oil valve limit switch, port boiler.
8. Adjusted #3 and #4 burner oil valve limit switches, port boiler.
9. Replaced LTR-7 relay, port boiler
10. Checked fire and ballast pump, Foxboro controller.
11. Operated boilers for setting and testing of safety valve, port boiler.

Report by: Frank Smith

cc: Accounting
Mr. H. Thompson