Monsanto

File

FROM (NAME & LOCATION): David Wood-St. Louis-B2SD

DATE : November 19, 1975

CC: T. Bottini
~~G. Levinskas~~
f/Spills, Bethlehem Steel

SUBJECT :

REFERENCE : BETHLEHEM STEEL
PYRANOL

TO : W. B. Papageorge
B2SK

Friday, the 14th of November, I had a call from Donald Webster of the Environmental Health Department in Bethlehem Steel, telephone: (215)694-4387.

An electro-magnet in one of their mines had a failure in the housing which resulted in the spill of some gallons of Pyranol PCB-containing insulation fluid.

We discussed clean-up, landfill, and incineration.

I suggested that it might be more suitable that the unit be repaired by the manufacturer or under the manufacturer's supervision rather than by Bethlehem Steel, themselves. The manufacturer is Stearn Magnetics.

We briefly discussed normal hygienic handling procedures, and I passed to Donald Webster, the name of Dr. Levinskas, should he need to make a contact with our Medical Department concerning two employees who were in contact with the Pyranol at the time of the spill.

David Wood

/deb

DSW 282961

STLCOPCB4064290