

October Activity Report

November 3, 1969

Cost estimates are being compiled by Process Engineering to determine the best method of manufacture.

2. The N/C tape drill installation and debugging has been completed. We have quoted 5 different mold plates for Plant 3 to be done on this machine. We have not received an order at this writing.
3. A relatively steady flow of information has been established with T.F. Victor. Their progress report to date indicates that they have converted 4 presses to the sandwich striker plate and are experiencing no production difficulties.

*R. T. Budovec*

R. T. Budovec

jm