INTRACOMPANY CORRESPONDENCE



TO: H. M. Cole

FROM: File

DEPT.:

DATE: May 8, 1973

SUBJECT: CORPORATE SAFETY COMMITTEE MEETING (5/7/73) - SUMMARY OF ASBESTOS SAMPLING DATA

	Results (Fibers/Ml)
Mixing asbestos shorts	3.0
Cleaning up insulation	1.9, 3.3
Removing insulation	3.1, 2.3
Wearing asbestos pads	0.05
Lining pot cradle	0.0. 0.0, 0.1
Background Sampling:	
Cast house	0.0
Pot room	0.0
Machine shop	0.0
Carpenter shop	0.036
Machining Operations:	
Marinite board - not heat treated	
Sawing, sabre	1.2, 1.8
skill	2.6
Drilling	0.7
Marinite board - heat treated	
Drilling	3.2, 20.0
Hand sawing	7.2

002500

TX TINER
RMC0086138