

Table of Chemical Hazards

are remarkably fast to washing, light and chemicals

VULCANIZATION Process of combining rubber (natural, synthetic or latex) with sulfur and accelerators in presence of zinc oxide

under heat and usually pressure in order to change the material permanently from a thermoplastic to a thermosetting composition, or from a plastic to an elastic condition. Strength, elasticity and abrasion resistance also are improved