11-143

37 Goldwick Crescent
London, Ontario.

March 1st, 1965.

Monsanto Canada Limited,
183 Front Street East,
Toronto 2, Ontario.

Dear Sir -

I would like to inquire on the possible ill effect of inerteen in a persons skin and lungs, etc.

The job that we are on, it is practically impossible to wear rubber gloves and we have not been supplied with any protectives for our faces.

Over the past while our faces have been stinging so badly that it was nearly impossible to get to sleep. The thing that is worrying us is if it burns our faces (when they haven't been touched), what is it doing to our lung etc., this is when the units and inerteen is cold. Quite often on the larger units the units and inerteen are approximately 250° F and this causes a tremendous amount of fumes to spread through the plant and causes considerable discomfort to people for 200 feet and the people working right in it.

Yours truly,

T. M. Steadman.

MONS 090434