



ENVIRONMENTAL
PROTECTION



SOUTH CHARLESTON PLANT

Bldg. 406 - 2nd. Floor
South Charleston, WV 25303

TO: J. K. Corrie

DATE: April 1, 1987

COPY: J. R. Soice
J. L. Worstell

SUBJECT: PROCEDURE REVIEW -
MAINTENANCE SAFETY
PROCEDURE XVIII -
ASBESTOS HANDLING

As discussed with you earlier today, EPD has reviewed the Asbestos Handling Procedure and has the following comments:

- ° On Page 16, in the first paragraph, the first sentence which states in part:

"....forms are to be approved and signed by the Environmental Protection Coordinator"

please delete "and signed" from said sentence.
- ° Include a requirement that an estimate of the total amount of asbestos wastes in units of cubic yards be given, in addition to square feet and linear feet. Estimates in terms of square feet and linear feet are required for the notification form (Appendix II, Page 17.) However, EPD is requiring an additional estimate in terms of total cubic yards of asbestos wastes for informational purposes for landfills.

Thank you for the review opportunity.


Dennis H. Hanshaw

DHH/rls
0085H

UCC 013298

