SURFACE TRANSPORTATION
ABERDEEN DISTRIBUTION FACILITY
FEBRUARY ACTIVITY REPORT, 1981

Shipment by Product - M/lbs.	February	Year-to-Date
Resin	19347	42478
Plasticizer	123	245
Dry Blend	4128	7227
Compound	3747	8086
Total	27345	58036

Number of Shipments by Mode

	R/C	O.T. BULK	O.T. VAN	C.O.T.	C.C.	TOFC	CPU	TOTAL
Resin - Bulk	73	41			26			140
Package			9				4	13
Export		1	121					122
Plasticizer							3	3
Dry Blend - Bulk	11	4			2		41	58
- Package			3				1	4
- Export			3					3
Compound - Bulk	7	9			5			21
- Package			18		7		9	34
- Export			18					18
Other - Antifreeze								
- Alumina								
Total	91	55	172	0	40	0	58	416
Back Hauls for February			32		3			35

Number of Shipment by Month-Year-to-Date

	R/C	BULK	VAN	C.O.T.	C.C.	TOFC	CPU	TOTAL
January	91	48	200	2	91	0	55	487
February	91	55	172	0	40	0	58	416

CONOCO TRANSPORTATION

ABERDEEN WAREHOUSE

LOCATION	TOTAL M SQ. FT.	CONTENTS		ESTIMATED MM POUNDS ON FLOOR	OPEN	TOTAL
MAIN-East	48	Compounds	4.5			
		Dry Blend	.3			
		Export Resin	.6			
		Conoco Resin	.2	5.6	4.4	10.0
Prairie 12-1	12	HDPE	.3	.7	.8	1.5
		Compound	.2			
		Dry Blend	.2			
12-2	22	Conoco Resin	3.1	3.1	.4	3.5
12-3	21	Conoco	.3			
		Export Resin	3.5	* 3.8	.	3.5
12-4	22	Conoco Resin	4.4			
		Resin O.G.	.	* 4.4	.	3.5
12-5	21	Mill Scraps	.1			
		Cmpd O.G.	.9			
		Dry Blend O.G.	.1			
		Sifter Overflow	.7			
		Resin O.G.	.8	* 2.6	.	2.5
12-6	21	Compound	.1			
		Resin	3.3			
		Raw Material	.3	* 3.7	.	3.5
12-7	21	Resin O.G.	3.6	* 3.6	.	3.5
12-8	21	Conoco Resin	4.5	* 4.5	.	3.5
12-9	21	Conoco Resin	2.9	2.9	.6	3.5
12-12	21	Dry Blend O.G.	.			
		Conoco Resin	.	.7	2.8	3.5
		S.O.	.4			
		Comp. O.G.	.3			
		Mill Scarp	.	.	.	3.5
		Sub-Total				42.0
		(Plug-Aisles)				2.6
Total	251	Total Conoco		35.6	9.0	44.6

DTH 000022109

ABERDEEN RAIL CAR REPORT

SURFACE TRANSPORTATION DEPT.

AS OF 2/27/81

LIMITS	LOCATION	LOADED VCM	EMPTY HOPPERS	LOADED HOPPERS	OTHER LOADS	TOTAL
35	IN PLANT	10	12	10	1	33
25	MONROE LEAD	18	15	3	3	39
20	BINFORD		2	15		17
	ICG DOWNTOWN					
	TEXICO TRACK		7			7
	SLSF ACROSS BRIDGE		2			2
	STRONG					
30	PRAIRIE		25			25
50	EGYPT			14		14
25	AMORY			3		3
	OTHER					
185	TOTALS	28	63	45	4	140

RECAP FOR MONTH

2/20/81	19	63	57	3	142
2/13/81	42	70	63	4	178
2/6/81	39	71	70	4	184
2/2/81	36	66	72	4	178

PAT WELLS

SAFETY REPORT

	February	Y.T.D.	GRAND TOTAL SINCE L.T.A.
Lost Time Accident	0		
Doctor Cases	0		
First-Aid Cases	0		
Man Hours Worked	3108	6099	175422

MATERIAL HANDLING REPORT

	M/lbs.	T/L
Packaged Resin From Production	7816	193
Packaged Compound, Dry Blend From Prod.	2795	69
Transferred From Main to Prairie	5143	127
Transferred From Prairie To Prairie	0	0
Reverse Transfer Resin to Plant	122	3
Reverse Transfer Cmpd. to Plant	283	7
Shipment from Warehouses	7411	183
Special Packaging	5751	142
Transferred From Prairie to Main	2714	67
Total	32035	791

LABOR REPORT

Total Regular Hours	2172
Total Overtime Hours	296
Total Worked	2468
Paid But not Worked	80
Total	2548

Labor Efficiency Equals

32.0 MM/Lbs. - Hours Worked 12,980

Overtime%

EQUIPMENT REPORT

Lift Truck Hours Worked	576
Gal of Fuel Consumed	489
Gals/Hrs	.8
Killowatt Hrs Year-To-Date	54927

Lift Truck Efficiency Equals
32.0 MM/Lbs. - Hours Worked - 55,616 Lbs./Hrs.

OFF-GRADE IN STORAGE

MATERIAL	M/LBS.	T/L
Sifter Overflow	1,188	29
Resin "BC"	3,293	81
Resin "H"	1,194	30
Mill Scraps	146	4
Compound "B"	1,309	32
Compound "H"	98	2
Dry Blend "O.G."	348	9
TOTAL	7,576	187

D.F. OPERATION

Shipments for the month were slightly off. Exports were down approximately 1.7 MM lbs. from previous month. Domestic shipments were down also.

We had an inventory build-up of approximately 2MM lbs. of primarily packaged resin.

Activity Report

Safety Meeting

The safety meeting for the month of February, 1981 was held at Goforth's Restaurant in Aberdeen, MS. The topic discussed was Donald Dove's accident and the proper steps to follow when filling out an accident report.

Recap of Out Bound Loads	Month	February
Our Truck	227	70 %
Other	0	0
Common Carrier	40	12
TOFC	0	0
Customer Pick-Up	58	18
	325	100 %

Equipment

Company pick-up, Unit #44880, has 115,592 miles as of 2-28-81.
The following trucks were overhauled during the month of February:

#1474 - 2-08-81
#1491 - 2-15-81
#1495 - 2-22-81

We ran three rental tractors and four rental trailers for the month of February.

Personnel

Richard Moreland put in a request for retirement, effective March 1, 1981.
Herbert Pearson hired as a casual driver.
All drivers liscense have been checked for violations.

Rail Activity Report

There were two derailments during February inside Conoco yard. Gatx 14177, a loaded PA car on 2/18/81 and Ptlx 41662, an empty hopper car, along with ICG engine 2/19/81. No injuries were reported connected with either derailment.

Van interstate truck load surcharge increased to 17% effective 2/6/81, to 18% effective 2/13/81, to 18½% effective 2/20/81, and to 19% effective 2/27/81.

Van intrastate rates increased 2/6/82 by ½%.

Rail intrastate and interstate receive a 2.2% surcharge effective 2/20/81.

ICG continues to work on Monroe lead with completion estimated March 6. 1981.