	Page
reducing	4-3
Unsafe conditions, reducing	4-3
Upsetters, forging	27-45
Uranium	
machining	42-20
toxicity	40-58

V

Vacuum breakers, unfired pressure vessel	16-21
Vacuum-handling trucks	
guards	20-5
operation	20-12
Valves, regulating and reducing	16-21
Vanadium pentoxide, toxicity	40-58
Vapor pressure (Reid method), definition	32-3
Vapor-proof lamps	14-16
Vapor volume, definition and listings	41-3
Vapors, cleaning	28-25
Vehicles, motor	
repair shops for	44-13
safety program for	44-2
Velocity duct	
control	28-5
minimum	28-14
Ventilation	
American Conference of Governmental Industrial Hygienists Committee on Industrial Ventilation	12-21
calculating degree for hazard control	41-2
comfort	28-50
controlling hazardous materials	39-38
design considerations	14-13
dilution	28-48, 39-38
drying ovens	27-18
in foundries	27-5
general	28-48
methods	28-55
requirements	28-1
Ventilation rates	
for industrial equipment, table	45-22
for metalworking and woodworking	45-27
for open-surface tanks, table	45-30
Venting, smoke and heat	33-7
Vents, storage tank	32-18
Vertical belts, guarding	22-23
Vertical conveyors	18-40
Vertical mixers for dough, guarding	28-3
Vertical shear, guard design	22-27
Vinyl chloride, toxicity	40-58
Vinyl propionate, toxicity	40-58
Vinylidene chleride toxicity	40-58
Visible radiation, effect on humans	39-16
Vitiation of air	28-50
Voice of safety—publicity	8-3
Volatility, definition	32-3
Voltages, arc welding	29-16

W

Walks moving	19-21
Walkways	
dimensions	14-19
maintenance	15-40
planning	14-4
(also see Aisles)	
Walls	
fire-resistive	14-10
foundation	15-34
maintenance	15-35
Warden service	35-25
Warehousing	17-11, 21
(also see Storage)	
Warfare, emergency plans for	35-5
Warning systems (see Alarms)	
Warnings, railroad clearance	19-24
Wash basins, industrial washroom	37-10
Wash fountains, industrial washroom	37-10
Wash rack operations, motor vehicle	44-15
Washers, textile, guarding	28-28
Washrooms, design and layout	37-9
Waste disposal, planning	14-5
Watchmen, plant security	35-20
Water	
disinfecting systems	37-5
potable	37-1
standards	37-3
storage	37-6
Water seals, unfired pressure vessel	16-21
Water spray systems, fire control	34-7
Water supply	37-1
fire extinguishment	34-1
Water systems, fire extinguishment	34-1
Water treatment, boiler feedwater	16-5
Waterways, waste disposal in	14-6
Weather-resistant luminaires	14-16
Welding and cutting	
American Welding Society	12-15
arc	29-15
as source of fire	33-13
eye filter lenses	36-17
in foundries	27-26
fume control	28-36
gas	29-2
gas-shielded arc	29-19
hazards	29-21
machines	29-18
other processes	29-21
personal protection	29-24
resistance	29-13
Wells, water supply	37-4
Wet collectors, dust	28-17
Wet pipe fire sprinkler systems	34-3
Wet water	34-13
Wharves, design	14-7
Wheel conveyors	18-39
Wheelbarrows, materials handling	17-10
Wheels	
abrasive (see Abrasive wheels)	
polishing and buffing	24-31
use of hand	30-19
wire brush	24-31
White fingers	39-14
Winches, hoisting	18-26
Wind, force for given velocities	15-6
Wind pressures, table	45-32
Window glass (See Glass, window)	
Windows, building	14-21
Windups, rubber industry, guarding	26-22
Wire brush wheels, safe operation	24-31
Wiring, electrical	14-17, 31-26
Women	
clothing and protection	36-51
health problems	38-7
protective caps	36-7
selective placement of	38-13
Wood-cutting tools	30-9
Wood, flameproofing of	33-28
Wood flooring	14-23
Woodworking	
dust control	28-38
machinery	25-1
ventilation rates, table	45-28
Work areas, inspection	2-12
Work-injury experience, significance of changes	9-21
Work practices, inspection	2-11
Work rests, abrasive wheel	24-27
Working conditions, on-the-job	38-19
Workmen's compensation laws	11-1
Workmen's safety committee	3-9
Wrapping machines for food, guarding	26-4
Wrenches, use of	30-12

X

X-rays, description	42-3
Xylenes, toxicity	40-59

Z

Zinc flooring	14-22
Zinc and zinc oxide, toxicity	40-59
Zirconium, toxicity	40-59