

Δ 53

Gypsum Association

201 North Wells Street, Chicago, Illinois 60608 (312) 725-5876

July 6, 1973

TO ALL MEMBERS OF THE
TECHNICAL COMMITTEE

Re: Asbestos in Joint Treatment Compound

Gentlemen:

The Board of Directors of the Association approved an investigation of the problem of hazards resulting from asbestos released in sanding and mixing joint compound. As a result, a meeting was held in Washington, D. C. with representatives of OSHA, in which they encouraged the Association to pursue a testing and monitoring program to determine the extent of hazards occurring in the use of joint compound as well as other effects of gypsum dust.

To date, Directors have responded to my report of the OSHA meeting dated July 11, 1973, with support and concurrence that the Association undertake a program to assess asbestos hazards in the use of joint compound.

Therefore, it is requested that available data be sent to me, for collection and consolidation, of investigations of the asbestos problem undertaken within the member companies. Also, it is requested that each company nominate a candidate to serve on an Association subcommittee to appraise the data, analyze the problem, and develop a monitoring program for presentation to OSHA that would reflect the consensus position of the Association's membership. The candidate proposed should have good knowledge of appropriate testing, screening, field application procedures, and possibly OSHA and NIOSH requirements. A four man subcommittee would seem practical. It is recommended that this subcommittee meet in August to begin the work.

Please give this your early consideration.

Yours very truly,

GYPSUM ASSOCIATION

H. B. Carlsen
H. B. Carlsen, Secretary
Technical Committee

HBC:mj

cc: Board of Directors
Chairman of all Committees



Δ 53

Gypsum Association

201 North Wells Street, Chicago, Illinois 60608 (312) 726-5876

July 6, 1973

TO ALL MEMBERS OF THE
TECHNICAL COMMITTEE

Re: Asbestos in Joint Treatment Compound

Gentlemen:

The Board of Directors of the Association approved an investigation of the problem of hazards resulting from asbestos released in sanding and mixing joint compound. As a result, a meeting was held in Washington, D. C. with representatives of OSHA, in which they encouraged the Association to pursue a testing and monitoring program to determine the extent of hazards occurring in the use of joint compound as well as other effects of gypsum dust.

To date, Directors have responded to my report of the OSHA meeting dated July 11, 1973, with support and concurrence that the Association undertake a program to assess asbestos hazards in the use of joint compound.

Therefore, it is requested that available data be sent to me, for collection and consolidation, of investigations of the asbestos problem undertaken within the member companies. Also, it is requested that each company nominate a candidate to serve on an Association subcommittee to appraise the data, analyze the problem, and develop a monitoring program for presentation to OSHA that would reflect the consensus position of the Association's membership. The candidate proposed should have good knowledge of appropriate testing, screening, field application procedures, and possibly OSHA and NIOSH requirements. A four man subcommittee would seem practical. It is recommended that this subcommittee meet in August to begin the work.

Please give this your early consideration.

Yours very truly,

GYPSUM ASSOCIATION

H. B. Carlsen
H. B. Carlsen, Secretary
Technical Committee

HBC:mj

cc: Board of Directors
Chairman of all Committees

