



Automotive

Bendix Friction Materials Division
P.O. Box 238
Troy, NY 12181
Telephone (518) 273-6550

*W.A.
F.Y.I.*

*Hand
11/10/86*

November 7, 1986

Vermont Container Corp.
P.O. Box 648
Bennington, VT 05201

Attention Mr. Ted Grant

Gentlemen

We wish to clarify the caution labelling to be printed on our cartons.

At present, as in the past, you are printing the following on all Ford Service Cartons:

CAUTION: Contains asbestos fibers.
Avoid creating dust. Breathing asbestos
dust may cause serious bodily harm.


When servicing this brake lining or
any component related to it or located
near it, prevent asbestos dust from
becoming airborne by vacuuming the
assembly with an industrial type
vacuum cleaner equipped with a high
efficiency filter system and by wash-
ing the assembly with an appropriate
brake parts washer, if necessary.
Never remove dust or dirt from this
assembly by blowing with compressed
air.

L1516

This should be continued as there is no change at the present time.

All other cartons, excluding General Motors and including Tri-Wall
Containers, must show the following statement:

DANGER
CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
CANCER AND LUNG DISEASE HAZARD



HWBUI0012434


Vermont Container Corp.
November 7, 1986
Page 2

This is the same statement you are presently printing with the deletion of the beginning sentence as shown on the enclosed sample.

We discussed all of the above with your representative on Thursday November 6, 1986 and asked that this change be accomplished immediately.

Please forward a letter indicating your agreement with our request, and advise when the change will be made.

Sincerely,

A handwritten signature in cursive script that reads "Guy H. Teats".

Guy H. Teats
Purchasing Supervisor

GHT/cl

cc: F. Schuttenhelm
C. Little
G. Thayer
W. Yetto
C. Larson
V. Keim
E. Rogers
R. Hart

RECEIVED NOV 10 1986

