you left off that night when you went home, if it wasn't finished, you went back into it to finish it off unless they wanted to start another team, like I said, drop somebody back white coating and they might say Cunningham, Jack, John, you go back white coating with that crew and then they would have a crew browning and a crew white coating. That is how they usually worked on them jobs.

They would have maybe 15, 16 men white coating, 15, 16 men browning and keep the brown moving for the white coat to follow up on.

Q Okay. So the white coat would be the last thing you would do.

Would that be one of the last --

A That is the finish coat.

Q Okay. Would the plasterers be one of the last people in the room when they did the white coat?

A Well, then you would have your carpenters come in and different other trades come in and do whatever they had to do in the room, put molding up, doors up or paint or whatever.