ALLIED Automotive

Bendix Friction Materials Division
P.O. Box 238
Troy, NY 12181
Telephone (518) 273-6550

RECEIVED
NOV 1 1 1986
C. R. LARSON

November 7, 1986

Vermont Container Corp.
P.O. Box 648
Bennington, VT 05201

Attention Mr. Ted Grant

Gentlemen

We wish to clarify the caution labelling to be printed on our cartons.

At present, as in the past, you are printing the following on all Ford Service Cartons:

> CAUTION: Contains asbestos fibers. Avoid creating dust. Breathing asbestos dust may cause serious bodily harm.
>
> When servicing this brake lining or any component related to it or located near it, prevent asbestos dust from becoming airborne by vacuuming the assembly with an industrial type vacuum cleaner equipped with a high efficiency filter system and by washing the assembly with an appropriate brake parts washer, if necessary. Never remove dust or dirt from this assembly by blowing with compressed air.
>
> L1516

This should be continued as there is no change at the present time.

All other cartons, excluding General Motors and including Tri-Wall Containers, must show the following statement:

DANGER
CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
CANCER AND LUNG DISEASE HAZARD

This is the same statement you are presently printing with the deletion of the beginning sentence as shown on the enclosed sample.

We discussed all of the above with your representative on Thursday November 6, 1986 and asked that this change be accomplished immediately.

Please forward a letter indicating your agreement with our request, and advise when the change will be made.

Sincerely,

Guy H. Teats

Guy H. Teats
Purchasing Supervisor

GHT/cl

cc: F. Schuttenhelm
C. Little
G. Thayer
W. Yetto
C. Larson
V. Keim
E. Rogers
R. Hart