B2SH P. G. Benignus

December 1, 1971

Leaky Askarel Drums

B2NK
E. M. POTTER

B2SA John Mason
B2SA H. S. Bergen
B2NK W. B. Papageorge
B2SL T. L. Gossage
B2SH C. Paton
1740 Art Leisy
1650 P. L. Slayton
1650 J. G. Bryant

WGK called today that two drums of Inerteen from a shipment to Boston Edison arrived empty.

Some time ago we met to point out that we have a faulty drum problem.

While we warn the user to spill none, we ship out some drums that spill their entire content.

Evidently the drum problem is not solved.

If this is not solved promptly with assurance we will have to stop drum shipment of PCB.

The sole reason the plant called was to get my views about forcing the customer to file claim for the lost material shipped on an FOB basis. On this basis by law the customer is responsible. This is ever more reason why Monsanto must either correct this drum problem or stop use of these containers.

Please advise all recipients of this memo as to where we stand.

Thank you.

P. G. Benignus

cs

DSW 180380