PLAINTIFF'S EXHIBIT
MON-1483

IN-10
MCC 930920

Monsanto

FROM (NAME & LOCATION) R. V. Sharp - Purchasing, Texas City PER (Ext. 3211)

DATE April 26, 1985

SUBJECT Second Quarterly Safety and Housekeeping Inspection - Depts. 48 & 56

REFERENCE

TO : V. Fields 56D
J. T. Shipley 56D

cc R. D. Coleman
H. M. Lacy
Jake Linkey
J. D. McPhail
R. E. Mears
SHAC

The overall condition of the units was good.

General Comments

1. Formal procedure for "bypassing protective devices" in place and working.
2. AVIP's - four (4) delinquent, but are scheduled. Variance letter for approval has been issued.
3. Plectron working O.K.
4. Employee knowledge of hazardous material handling satisfactory.

Department 48

Safety

1. Oil load rack - drum of lubricant not grounded.
2. Full drum of Ispropyl Alcohol - half-on, half-off pallet at oil load rack.
3. Steam line (3/4") just east of oil load rack - needs insulation.
4. Cylinders next to 48T407 - safety chain is partially wired.
5. Hoses next to 48T407 need inspection.
6. Elevator with pallet and barrel at first level without safety chains hooked.

Housekeeping

1. Hinge broken on 5 minute escape mask cabinet - 2nd level Oxo. distillation.
2. Insulation wire hanging on sight glass north of 48E501.
3. Sheet metal on ground in northeast corner of fin fans.

Department 56

Safety

1. Scaffold west of 56V1-1 with no toe board.
2. Hoses not inspected properly (next to 56T3-3 & 56T3-1).
3. Two drums not grounded in liquid waste drum area.

Housekeeping

1. Sample catcher with rope on 2nd floor on top of of T3-3.
2. Liquid waste drum area - nasty looking, needs clean-up.
3. Maintenance shack (Dept. 56) - sad state of repair (drums outside - rusted out - very poor condition).
4. Plugged drain west of 56E10-1 & 2.
5. Steam hose on ground south of 56P18.
6. Clutter on 1st level of 56 - on west side boards and rope with chain.

Please respond in writing to Doug Barfoot and Jim McPhail by May 17, 1985.

R. V. Sharp

RVS:wy