PLAINTIFF'S
EXHIBIT
DUP-2542

EVALUATION OF ASBESTOS CONTROL IS INCLUDED IN S & F'S OCCUPATIONAL HEALTH SURVEYS. WE HAVE FOUND:

- THE CORPORATION IS NOT UNIFORM IN CONTROLLING ASBESTOS HANDLING PRACTICES.
- WRITTEN PROCEDURES FOR HANDLING ASBESTOS ARE NOT COMPLETE FOR ALL SITES. THOSE THAT ARE COMPLETE ARE GENERALLY GOOD.
- AIR SAMPLING IS NOT ALWAYS USED TO CONFIRM THAT RESPIRATORS ARE NOT NEEDED ON NON-DUSTY ASBESTOS HANDLING JOBS.
- THE WET METHOD FOR HANDLING ASBESTOS (WHICH SHOULD BE USED WHENEVER "PRACTICABLE") IS NOT ALWAYS USED IF THE JOB IS NOT CONSIDERED DUSTY.
- MORE ASBESTOS LEVEL MONITORING IS NEEDED.
- CONTROL IS REQUIRED FOR SOME LESS OBVIOUS SOURCES OF ASBESTOS SUCH AS WELDING CURTAINS.

DUP 0821281

plyed. A variety of signs and terminology are used for the s...
Chemical - T... and it is recommended that a
uniform approach to design of cautionary signs be developed.

Asbestos is present on the Plant in the form of gaskets and
ld insulation, cloth and tape on equipment. A commendable job
has been done to remove asbestos from the Plant. ~~Apart from~~
few items such as asbestos glove..., and Laboratory supports com...
ith asbestos cloth and Asbestos - a Laboratory sergeant - were found which
ld to be addressed. Installations of asbestos tape and insulation appear
be in good condition. Demolition of equipment containing asbestos
ulat by a contractor was well controlled and personnel monitoring for
estos fibres was conducted. The Plant procedure for handling asbesto
being revised and embodies recent guidelines. Eng Std S4T.
ecently asbestos handling is being revised & should wise shortly. The
rk should review this new issue of S4T to ensure that Plant procedures m
line. Monitoring should be continued for asbestos fibres wherever
ticable to develop data demonstrating compliance with the current standard

Ventilation.

A good program exists to routinely check the airflow in
ab fume hoods & local exhaust ventilation units. Central Shops plans
upgrade the local exhaust facilities for welding booths and the lathe.
commendations were made for annual calibration of the velocities. New
ume hoods are to be installed in Hlethan Laboratory & it is recommend
hat personnel discuss this with LSD specialists at Wellington Eng Dept
be aware of most recent information on design & performance of hoods

DUP 0821282