Monsanto

DICTATE IN SEQUENCE:
1. HEADING INFORMATION
2. NAMES OF ADDRESSEES
3. NAMES OF CARBONEES
4. IMMEDIATE ACTION NEEDED
5. REPORT ON CALL

REPORT CAPTIONS:
1. OBJECTIVE
2. PERSONS CONTACTED
3. RESULTS
4. ACTION REQUIRED

CUSTOMER NAME					DATE OF CALL
CHEMICAL PRODUCTS CORP.					6/2/70
CITY AND STATE			DATE RECEIVED		DATE TYPED
RUMFORD, RHODE ISLAND			6/4/70		6/4/70
CUSTOMER MAILING LIST CHANGES – SERVICE CENTER USE ONLY					
NAME AND TITLE	PUT ON	TAKE OFF	MP	MAG.	CATEGORY CODES
REGION	SERVICE CENTER		SALESMAN		
NORTHEAST	Everett		D.L. Mellon/ims		

TO MR. WILLIS CLARK
ST. LOUIS

CC J. K. LILLY-ST. LOUIS
E. L. KAISER "

PERSONNEL CONTACTED: George Fountas, Technical Director

RESULTS:

1. Aroclor 5460/1221 -Recommended Aroclor 1221/5460 blend to replace 10,000 pounds Aroclor 1254 utilized annually by Chemical Products. Aroclor 1254 was used exclusively in cellulosic lacquer utilized to meet Military Specs. for lacquer used in wire and cable applications.

2. ODORLESS DOP - Fountas indicated odorless DOP potential at Chemical Products is in excess of 1M lbs.

3. REGULAR DOP - Fountas indicated regular DOP potential at Chemical Products in excess of 3M lbs. annually.

4. DIDP - Fountas indicated the potential for DIDP in excess of 1M lbs. annually.

FURTHER ACTION REQUIRED:

1. Monitor Aroclor 5460/1221 as Aroclor 1254 replacement
2. Submit Texas City odorless DOP for evaluation.

S-331 (REV. 12/68)

1 – CENTRAL OFFICE COPY

DSW 468157

TOWOLDMON0054724