

## A U T O M O T I V E   D A T A   B O O K   B U L L E T I N #6-931

March 30, 1994

This is the last Automotive Data Book Bulletin before copy was sent to the printer for the 1994 Automotive Data Book.

|                                     |            | FRONT<br>FMSI NO.       | SYSTEM<br>F/R | REAR<br>FMSI NO. |
|-------------------------------------|------------|-------------------------|---------------|------------------|
| <u>BMW (See Corrections)</u>        |            |                         |               |                  |
| 1994, 318i                          |            |                         | /D            | 7396-D517**      |
| 1994, 325i                          |            |                         | /D            | 7396-D517**      |
| 1994, 850CSi                        |            | 7426-D547**             | D/            |                  |
| <u>CHEVROLET TRUCK</u>              |            |                         |               |                  |
| Kodiak C6H042                       | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| Topkick C6H042                      | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| Kodiak C7H042                       | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| Topkick C7H042                      | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| <u>DODGE (See Corrections)</u>      |            |                         |               |                  |
| 1994(late), Caravan                 |            | 7470A-D591              | D/BH          | 2176T-538        |
| 1995, Neon                          |            | 7518A-D642<br>(Note #3) | D/            |                  |
| <u>DODGE TRUCK</u>                  |            |                         |               |                  |
| Caravan C/V                         | 1994(late) | 7470A-D591              | D/BH          | 2176T-538        |
| <u>FORD</u>                         |            |                         |               |                  |
| 1994, Probe                         |            | 7463-D583**             | D/N           | 1407-S667*       |
|                                     | OR         | 7515-D637**             | D/D           | 7464-D584**      |
| <u>FORD TRUCK (See Corrections)</u> |            |                         |               |                  |
| F350                                | 1994       |                         |               |                  |
|                                     |            | 7330-D450**             | D/BH          | 2140AT-314       |
|                                     | OR         |                         | /BH           | 2171T-583*       |
| <u>GMC TRUCK</u>                    |            |                         |               |                  |
| Topkick C6H042                      | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| Topkick C7H042                      | 1993-92    | 7818-D225**             | D/D           | 7818-D225**      |
| <u>HONDA</u>                        |            |                         |               |                  |
| 1994, Accord Wagon                  |            |                         | /N            | 1429-S627*       |
|                                     | OR         |                         | /D            | 7418-D537**      |
| <u>HYUNDAI</u>                      |            |                         |               |                  |
| 1994, Elantra                       |            | 7329-D449**             | D/D           | 7344-D464**      |
| 1994, Excel                         |            |                         | /N            | 1451-S663*       |
| 1994, Scoupe                        |            |                         | /N            | 1451-S663*       |
| <u>LAND ROVER</u>                   |            |                         |               |                  |
| 1994, Range Rover County            |            | 7401-D520**             | D/D           | 7399-D518**      |
| 1994, Range Rover County LWB        |            | 7401-D520**             | D/D           | 7399-D518**      |
| <u>MERCEDES</u>                     |            |                         |               |                  |
| 1994, E320                          |            | 7440-D561**             | D/            |                  |
| 1994, S320                          |            | 7440-D561**             | D/            |                  |
| <u>MITSUBISHI</u>                   |            |                         |               |                  |
| 1994, Galant                        |            |                         | /N            | 1445-S658*       |
| <u>NEOPLAN</u>                      |            |                         |               |                  |
| Transit Bus 410 x 160               |            | 4712<br>(Note #2)       |               | 4712             |
| <u>NISSAN</u>                       |            |                         |               |                  |
| 1994, Maxima                        |            | 7407-D526**             | D/N           | 1381-607*        |
| 1994, Pathfinder                    |            | 7228-D333**             | D/D           | 7290-D401**      |
| <u>PLYMOUTH (See Corrections)</u>   |            |                         |               |                  |
| 1994(late), Voyager                 |            | 7470A-D591              | D/BH          | 2176T-538        |
| 1995, Neon                          |            | 7518A-D642              | D/            |                  |

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

March 30, 1994

|                        | FRONT<br>FMSI NO. | SYSTEM<br>F/R | REAR<br>FMSI NO.  |
|------------------------|-------------------|---------------|-------------------|
| <b>PORSCHE</b>         |                   |               |                   |
| 1994, 911 Carrera 2    | 7326-D608**       | D/D           | 7326-D608**       |
| 1994, 911 Carrera 4    | 7238-D345**       | D/D           | 7238-D345**       |
|                        | OR 7327-D447**    | D/D           | 7327-D447**       |
| 1994, 911 Turbo        | 7473-D594**       | D/D           | 7238-D345**       |
|                        | OR                | /D            | 7326-D446**       |
| 1994, 928              | 7326-D446**       | D/D           | 7326-D446**       |
| 1994, 968              | 7327-D447**       | D/D           | 7238-D345**       |
| <b>SAAB</b>            |                   |               |                   |
| 1994, 9000             | 7292-D403**       | D/D           | 7221-D322**       |
| <b>THEURER TRAILER</b> |                   |               |                   |
| 420 x 180              |                   | /A            | 1477<br>(Note #1) |
| <b>TOYOTA</b>          |                   |               |                   |
| 1994, MR2              | 7153-D242**       | D/D           | 7409-D528**       |
| 1994, MR2 Turbo        | 7462-D582**       | D/            |                   |
| <b>VOLKSWAGEN</b>      |                   |               |                   |
| 1994, Golf III         | 7177-D227**       | D/N           | 1450-S662         |
|                        | OR                | /D            | 7234-D340**       |
| 1994, Golf GTI         | 7177-D227**       | D/D           | 7234-D340**       |
| 1994, Jetta III        | 7177-D227**       | D/N           | 1450-S662         |
|                        | OR                | /D            | 7234-D340**       |
| 1994, Jetta III GLX    | 7143-D590**       | D/D           | 7234-D340**       |

**CORRECTIONS**

Bulletin #5-931 incorrectly listed BMW 850CSI front brake. The correct listing is FMSI 7426-D547.

Bulletin #5-931 incorrectly listed Ford Truck F350 rear brake. The correct listing is FMSI 2140AT-314.

Bulletin #5-931 incorrectly listed 1995 Dodge/Plymouth Neon 14" wheels front as 7518A-D591. The correct listing is 7518A-D642.

**DRUM BRAKE LINING ASSIGNMENTS**

Note #1

FMSI 1477:

420.0dd - 179.8 x 16.9 x 223.2 8 - 80  
 Tapered  
 (16.54 - 7.08 x .665 x 8.79)  
 Tapered

**BRAKE BLOCK LINING ASSIGNMENTS**

Note #2

FMSI 4712

410.0 - 159.5 x 19.0 x 208.8 4 3/8R 64  
 Tapered x 215.9 4  
 (16.14 - 6.28 x .750 x 8.22)  
 Tapered x 8.50)

**DISC BRAKE SHOE ASSIGNMENTS**

Note #3

FMS D642

165.1 x 5.3  
 165.1 x 4.7  
 (6.50 x .209)  
 (6.50 x .185)

7518A-D642  
 Dodge  
 Plymouth

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.