Reviewed with Johnson, J May, teams 10/9/8

1. Our blood lead levels do not indicate we have a 50 ug level behind the respirator

OSHA stats

above 60 -	0	0
50-60	1	8
40-50	27	7
below 40 -	19	10

2. We spent $30,000 in legal fees last time plus cost of taking, read etc.
This is 10-15% of our profit
Can we afford this

3 NO FACIAL HAIR

4 Airborne lead dust levels must come down

5 To get money we must assure blood lead levels below 50

6 Keep all containers covered

7 Better vacuuming

8 Must enforce the locker room systems

9. Much concern about our our ineffectiveness in controlling the plant and Xyzyx pyrogram

CYWI 3-000954

MUST DC

1 reduce blood leads
2 improve work habits to reduce dust
3 wipe samples
4 send out letter on airborne lead dust

1. stand alone business

2. Cost of doing Ton Oilings report - (MUST) !!
   a) need for OSHA
   b) Call Q 2? Carl Cormine

3 Paint batteries different colors to determine usage

4