

10 / 11 / 79

Reactors

1. Charging: 5385 Old Unit
 741 - 5425 (Break with 5385 as needed)
 742 - 5305 (Until L-11 is gone) then 5385
 743 - 5385
 744 - 5385 EXP - BLADE CHANGE

2. Increased temperature on 5305 10

3. When 744 is ready for a blade change notify Maint. (30 min before you're ready) The blade change takes priority.

Special Instructions:

1. Chem Wash, rinse and full swirl 744 before you open it for entry.
2. Follow the Engineering Work Practice Control Plan.
3. Fill out vessel entry checksheet.
4. May have to reduce cat. loading if weather warms.

Dyers

1. Pump over 646
2. Have 677 empty at 7AM for maint. on bottom valve.
3. Bag 3 lines on 5385. 5305 to 680 silo for a railcar.
- * 4. You need to stamp the "Cancer Causing Agent" stamps on the C-6 bags. C-5's should be in anytime.

DTH 000081241

Altman
see note
on desk.

General

1. Alton - Safety Meeting
2. Keep up the good work

Alton 3. FRYE DOES NOT HAVE TO COME FOR STOCKS

1400 0700

Received 10/11/79

(1) all present

(2) #3 leaving work. H154 was out of time called in
H154 report for repair just some joints OK.

(3)