B-A-C p.c.

UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

To: Mr. L. D. Diggs
Mr. J. G. Roy
Mr. A. E. Thompson
Mr. C. L. Thompson
Mr. R. Vega

December 14, 1983

Copy to: Mr. J. J. Ashworth
Mr. W. E. Ballard
Mr. C. E. Fry
Mr. C. R. Gillespie
Mr. E. G. Hager
Mr. E. O. Harrah
Mr. J. V. Pittman
Mr. W. B. Spurlock
Mr. T. G. Swanson
Mr. R. L. Taylor
Shift Superintendents
ES Routing Lists 2, 3 & 4

ES Department
Asbestos Handling
Procedures

As part of our continuing effort to tighten control of Safety/Health risks in the Energy Systems Department, I would like to implement the following requirements until I'm satisfied we have full compliance with Plant asbestos handling procedures in our Department:

- Any removal of insulation potentially containing asbestos in ES requires a Class "A" Hazardous Work Permit.

- Removal of any thermal insulation in ES whether or not it contains asbestos requires the wearing of dust respirators and barricade taping of exposure area.

These requirements are in addition to the Plant's current requirements and will be maintained in ES until further notification.

Thanks,

Bob Ream

R. A. Ream

RAR:kab

PLAINTIFF'S EXHIBIT
UC-4259