To: Harry Ray

Date 4/15/68

The following message was recorded on AIR in reference to an air emission which appears to have come from your department. Please investigate and reply (on the right side of this form), advising what caused the emission and what corrective action has been, or will be, taken to prevent recurrence.

MESSAGE:

1:30 P.M. MONDAY
STRONG EYE-SMARTING
BIPHENYL ODOR SOUTH SIDE OF PARKING LOT.
APPEARS TO BE WHITE PLUME FROM A TANK ON
THE NORTH SIDE OF 254

Is it practical to release this air slowly, or would this help?

Dalton

Original to C. F. Buckley
1 copy to C. F. Buckley
1 copy to Superintendent

0029

SUPERVISOR: Please reply below. No carbon paper is necessary. After completion, mail the original and 1 white copy to C. Buckley TSD who will forward a copy to the person who reported the emission. Forward the remaining copy to your superintendent.

CIRCUMSTANCES:

A Biphenyl car was unloaded by air on 4-15-68. It went empty at approx. 1 PM. When the car blows empty the pressure on the car is shut off into the atmosphere. Some Biphenyl is present in the air, in the car, and is released with the air.

2 or 3 cars are unloaded each week.

CORRECTIVE ACTION (indicate Projects, investigations etc. and expected date of completion):

No project or investigation is under-way at this time.

Signature: V. Brawley H. Ray
Dept 246

DSW 345412

STLCOPCB4084084