PLAINTIFF'S EXHIBIT

MAR-87

200 EAST RANDOLPH DRIVE, CHICAGO, ILLINOIS 60601 • 312/861-4000

MAREMONT
CORPORATION

October 21, 1980

Mrs. T. B. Flannery
Assistant Buyer
Auto Accessories, Department 628
Sears, Roebuck and Company
Sears Tower
Chicago, IL 60684

RE: OSHA Asbestos Warning
Sears Packaging

Dear Terry:

Confirming our phone conversation of October 13, we will include the following warning on the revised instruction sheets packaged in all of the Sears brake kits.

Printed on the carton itself will be the following:

"IMPORTANT INSTRUCTIONS ENCLOSED - PLEASE READ"

Very truly yours,

W. N. Bockay
Division Manager
Brakes

WNB/sp
Enc.

cc: W. C. Burkhead
L. J. Hatfield
D. L. Levans
D. R. Loftis
J. L. Mellow
R. C. Rogers
R. L. Seward
J. H. Sherr

NO. P-35
DATE 1-10-84
EVD. ☐ IDENT ☒

11 98

CAUTION - ASBESTOS DUST HAZARD

**Contains Asbestos Fibers**

**Avoid Creating Dust**

**Breathing Asbestos Dust May Cause Serious Bodily Harm**

-oOo-

Dust hazards may exist if mishandled when installing, removing, or machining. Use safe techniques and approved equipment. For further information, contact P.O. Box 737, Antioch, TN 37013