

Monsanto

FROM (NAME & LOCATION)

J. J. McClellan - O-11

DATE

January 22, 1982

cc. T. Ozarchuk

M. Riddle

SUBJECT

Hourly Safety Committee Meeting
January, 1982

REFERENCE

TO

W. E. Bean - SS-4 ✓
J. M. Burkhalter - SS-10 ✓
Gene Crain - SS-8 ✓
A. J. Davidson - SS-10 ✓
L. E. Derrick - AB ✓
Lawrence Elbert - 35F ✓
Clarence Jackson - 51D ✓
James H. Martin - 2PD ✓
Walt Middleton - SS-13 ✓
Ruby Mosley - SS-22 ✓
Carl Richardson - 19D ✓
R. L. Sartain - SS-12X
Mike Westmoreland - AB-1 ✓

Don Metten
Dennis Kos
Joe McClellan
Mark Riddle

The first Hourly Safety Committee meeting for 1982 will be held Tuesday, January 26, 1982, at 1:30 p.m., in the Personnel Building Conference Room No. 1.

The members for the last six months of 1981 and the new 1982 members should attend.

J. J. McClellan

J. J. McClellan
SHAC Chairman

lw

SC

12990

LAM014207

HSC - 1/26/82

DUG METTEN:

- FALL-80
- 1st QTR-81
- SUMMER-81 (PRE-INSP.)
- 4th QTR-81
- COUNTDOWN-82

DENNIS KOS - NEW CHAIRMAN


ELECTION - CARL RICHARDSON (X-2511)

RICKY SARTAIN'S BIKE

HATS FOR NEW MEMBERS:

WALT
GENE
~~MIKE~~ MIKE
CARL
A.J.

CARL - PARKING OF REFUELING TRUCK ON ST. ON EAST SIDE OF GARAGE
2nd St. heading S into South St.



GENE - Parking on S side of shop
- Dumpster

GENE - 7 1/2 Ton Crane } will go back to CRAFT TEAM
Stability }

- H₂O Blasting Rigs - coming into plant with unguarded fans, belts, etc.

- AN in Breathing Air @ 51
Alarm for contamination, communication

MIKE - 51 INCIDENT - PULLING BLINDS W/0 HEADING UP (MANUALLY CTF) - WHAT ARE PLANS? DISCUSSED IN HSC MEETING IN FEB.

- Reviewed proc. & stop-work and communication were made
- Requiring special permit
- No change in permit proc.

CARL:

- No driveway at Cafeteria - needs stop sign
- Crosswalk non-existent
- "No thru traffic"

Wait: 35 T-22-10

Penicillin

"Explosion suppression system" -
not blocked in - removed people
from tank 'til they did

→ Review of incidents at HSC meeting?

→ Including HSC members on incident investigations?

CARL:

WINDSHIELD WASHERS DON'T WORK -
DRIVE THRU ^{CAR} WASHER

RUBY:

CONTROL LAB

BREAK BOTTLES ; FAN
VENTILATION IS COLD
RECOMMEND HOOD

"BOTTLE CRUSHING AREA"

FUMES ARE BAD -

PROD. VS. SAFETY VS. STRIKE VS. SAFETY
(OPPOSITE EXTREMES)

SC

12991

LAM014208