

Meeting of 12/15/86

10,000 ft²

1 mo. to remove insulation
2/basket 2 cranes
BWE - 5000 wetting agent
10 hrs/day 7 days/wk

120 ft. high

Ralph Painter - 1st line supervisor
Homer Rucker - 2nd line supervisor

Shut down of cooling fan on columns.

Medical approval

Check w/ER into whether a break is mandatory.

Charlie Brown covering asbestos landfill on weekends?

Wed. Dec. 17th w/ Homer & Mark

Fri. Dec. 19th w/ Don, John, Homer and Bud @ 1:00