TB 442

D4.TXT

6,434

DATE:
REVISED DATE:07/23/86

ST0175772

MIXING PULP [redacted] LONG FIBER AND 7M SHORT FIBER

JOB TYPE:

ROUTINE

PERMITS REQUIRED:

NONE

POTENTIAL HAZARDS:

FALLS,PINCH POINTS, SLIPPERY SURFACE, BODY POSITIONS AND ASBESTOES

~~EXPLANATION OF HAZARDS:~~

~~FALLS~~ BE AWARE OF TRIPPING HAZARDS; ~~PINCH POINTS~~- HANDLING SACKS AND OPERATING VALVES; ~~SLIPPERY SURFACE~~- WET FLOOR AND ASBESTOES; ~~BODY POSITIONS~~- HANDLING ASBESTOES SACKS; ~~ASBESTOES~~- DUST HAZARD- AVOID BREATHING DUST; WEAR ASSIGNED PROTECTIVE EQUIPMENT. DO NOT REMAIN IN AREA UNLESS YOUR WORK REQUIRES IT. BREATHING ASBESTOES ~~MAY BE~~ IS HAZARDOUS TO YOUR HEALTH.

SAFETY [redacted]

HARD HAT, RESPIRATOR, SIDESHIELD GLASSES, ~~HEARING PROTECTION,~~ MONOGOGGLES, CHEMICAL GLOVES, WHITE SUIT, ~~DUST MASK,~~ AND RUBBER BOOTS.

CONFO WITH APPROVED F. TERS OR FORCED AIR RESPIRATOR

SPECIAL TOOLS:

NONE

REFERENCES:

NONE

OTHERS:

ASBESTO[redacted] LOCATED IN THE HAZARD COMMUNCATION MANUAL.

JOB PROCEDURE BY STEPS:

RED TAG AND LOCK OUT PROCEDURES
MIXING PULP 3F-700 LONG FIBER AND 7M SHORT FIBER

TO RED TAG P-518A:
1. CLOSE SUCTION VALVE AND TAG.

PLAINTIFF'S EXHIBIT

DOW-886