

6. Evaluate the possibilities of lamination for the 1/16" gauge from a cost and processing standpoint. Manufacturing should initiate.
7. Determine if the use of alum, hot water, ideal felt, etc., will allow the use of all 6DO2 fiber as was originally used. Van Sebastian to initiate.



VL:pt