

FRICITION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468
 A U T O M O T I V E D A T A B O O K B U L L E T I N #4-951
 April 26, 1996

This is the last Automotive Data Book Bulletin before copy was sent to the printer for the 1996 Automotive Data Book.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1996, NSX-T	7382-D503**	D/D	7383-D504**
1996, SLX	7459-D579**	D/D	7460-D580**
<u>BMW</u>			
1996, M-3	7284-D394**	D/D	7286-D396**
1996, 740iL	7560-D681**	D/D	7427-D683**
1996, 750iL	7561-D682**	D/D	7427-D683**
1996, 840Ci		/D	7427-D548**
1996, 850Ci		/D	7427-D548**
<u>CHEVROLET</u>			
1996, Lumina Minivan	7384-D623**	D/N	1394-S636
<u>CHEVROLET TRUCK/GMC TRUCK</u>			
Blazer/Jimmy 1996	7480A-D202	D/BH	2117BTT-S651
S10/Sonoma 1996	7480A-D202	D/BH	2117BTT-S651
T10/Sonoma 4WD 1996	7480A-D202	D/BH	2117BTT-S651
C1500/Sierra 1500 1996	7259-D369**	D/N	1404A-S675
C2500/Sierra 2500 1996	7259-D369**	D/BH	2073AT-S653
	OR 7260-D370**	D/BH	2042BT-S655
C3500/Sierra 3500 1996	7260-D370**	D/BH	2042BT-S655
	OR 7339-D459**	D/BH	2157AT-S656
C3500 DRW/Sierra 3500DRW 1996	7339-D459**	D/BH	2157AT-S656
	OR 7815-D380**	D/D	7815-D380**
K1500/Sierra 1500 4WD 1996	7259-D369**	D/BH	2073AT-S653
K2500/Sierra 2500 4WD 1996	7259-D369**	D/BH	2073AT-S653
	OR 7260-D370**	D/BH	2042BT-S655
	OR /BH		2157AT-S656
K3500/Sierra 3500 4WD 1996	7260-D370**	D/BH	2157AT-S656
	OR 7339-D459**	D/	
Tahoe/Yukon 1996	7259-D369**	D/N	1404A-S675
	OR 7260-D370**	D/BH	2073AT-S653
Suburban 1500 1996	7259-D369**	D/BH	2073AT-S653
	OR 7260-D370**	D/BH	2157AT-S656
Suburban 2500 1996	7259-D369**	D/BH	2073AT-S653
	OR 7260-D370**	D/BH	2157AT-S656
Astro/Safari 1996	7214A-D52	D/BH	2117BTT-S651
Astro 4WD/Safari 4WD 1996	7259-D369**	D/BH	2117BTT-S651

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.	
<u>CHRYSLER (See Corrections)</u>					
1996(Early), Town & Country			/N	1485TT-S703 (Note #5)	
1996(Early), Town & County AWD			/N	1485TT-S703	
1996(Late), Town & Country	7470A-D642	D/N		1485ATT-S714 (Notes #6 & #14)	
1996(Late), Town & County AWD	7470A-D642	D/N		1485ATT-S714	
1996, Sebring Convertible	7530A-D650	D/N		1449-520	
<u>DODGE (See Corrections)</u>					
1996(Early), Caravan			/N	1485TT-S703	
1996(Early), Grand Caravan			/N	1485TT-S703	
1996(Early), Grand Caravan AWD			/N	1485TT-S703	
1996(Late), Caravan	7470A-D642	D/N		1485ATT-S714	
1996(Late), Grand Caravan	7470A-D642	D/N		1485ATT-S714	
1996(Late), Grand Caravan AWD	7470A-D642	D/N		1485ATT-S714	
<u>EAGLE</u>					
1996, Talon			/N	1445-S658*	
<u>FORD</u>					
1996, Probe		7515-D637**	D/N	1407-S667*	
	OR		/D	7464-D584**	
<u>FORD TRUCK</u>					
Bronco	1996	7503-D632**	D/BH	2141AT-582	
E-250	1996	7535-D655**	D/BH	2146T-316	
		OR	/BH	2140AT-314	
E-350	1996	7535-D655**	D/BH	2140AT-314	
		OR	/BH	2178T-583*	
F-250	1996	7535-D655**	D/BH	2146T-316	
		OR	/BH	2140AT-314	
F-350	1996	7535-D655**	D/BH	2140AT-314	
		OR	/BH	2178T-583*	
F-450	1996	7299-D411**	D/D	7299-D411**	
<u>HONDA</u>					
1996, Civic		7439-D560**	D/N	1379-S639*	
		OR	7493-D617**	D/N	1364-576*
		OR	/D	7443-D564**	
1996, Civic del Sol		7439-D560**	D/N	1379-S639*	
		OR	7493-D617**	D/D	7443-D564**
<u>ISUZU</u>					
1996, Trooper		7459-D579**	D/D	7460-D580**	
<u>LAND ROVER</u>					
1995-92, Defender 110			/N	1494-S713* (Notes #7 & #13)	
<u>LEXUS</u>					
1996, ES300		7357-D476**	D/D	7223-D325**	
1996, GS300		7495-D619**	D/D	7452-D572**	
1996, SC300			/D	7452-D572**	

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>LEXUS (con't)</u>			
1996, LS400	7544-D665**	D/D	7491-D613**
1996, LX450	7298-D502**	D/D	7487-D606**
1996, SC400	7451-D571**	D/D	7452-D572**
<u>LINCOLN</u>			
1996, Town Car	7537-D678**	D/	
<u>MAZDA</u>			
1996, MX6	7515-D637**	D/N	1407-S667*
	OR	/D	7464-D584**
1996, 626	7515-D637**	D/N	1407-S667*
	OR	/D	7464-D584**
<u>MERCURY</u>			
1996, Mountaineer	7532-D652**	D/D	7545A-D667
<u>MITSUBISHI</u>			
1996, Montero	7412-D530**	D/D	7447-D567**
<u>NISSAN (See Corrections)</u>			
1996, 240SX	7307-D422**	D/	
1996, 300ZX		/D	7341-D461**
1996, Maxima		/D	7533-D540**
1996, Quest	7456-D576**	D/	
1996, Pick-up	7282-D441**	D/N	1399-574*
	OR 7228-D333**	D/N	1433-S631*
<u>OLDSMOBILE</u>			
1996, Bravada	7480A-D202	D/BH	2117BTT-S651
1996, Silhouette	7384-D623**	D/N	1394-S636
<u>PLYMOUTH (See Corrections)</u>			
1996(Early), Voyager		/N	1485TT-S703
1996(Early), Grand Voyager		/N	1485TT-S703
1996(Early), Grand Voyager AWD		/N	1485TT-S703
1996(Late), Voyager	7470A-D642	D/N	1485ATT-S714
1996(Late), Grand Voyager	7470A-D642	D/N	1485ATT-S714
1996(Late), Grand Voyager AWD	7470A-D642	D/N	1485ATT-S714
<u>PONTIAC</u>			
1996, Trans Sport	7384-D623**	D/N	1394-S636
<u>PORSCHE</u>			
1996, 911 Turbo	7473-D594**	D/D	7327-D447**
<u>SAAB</u>			
1996, 900	7522-D644**	D/D	7316-D427**
1996, 9000	7292-D403**	D/D	7221-D322**
<u>SATURN</u>			
1996, All	7386-D507**	D/N	1437-S637*
	OR	/D	7387-D508**

	FRONT	SYSTEM	REAR
	FMSI NO.	F/R	FMSI NO.

SUZUKI

1996, Swift	7331-D451**	D/N	1489-608*
1996, Sidekick 2DR	7305-D418**	D/	

TOYOTA (See Comments)

1996, Avalon	7357-D476**	D/D	7553-D672**
1996, Camry	7441-D562**	D/N	1447-587*
	OR 7357-D476**	D/D	7223-D325**
1996, Celica	7441-D562**	D/N	8104-588*
1996, Corolla	7441-D562**	D/N	8105-597*
1996, Paseo	7153-D242**	D/N	1439-S642*
1996, Supra	7495-D619**	D/D	7491-D613**
1996, Supra Turbo	7508-D629**	D/D	7509-D630**
1996, Tercel	7153-D242**	D/N	1439-S642*
1996, Previa	7408-D616**	D/	
	OR 7380-D615**	D/D	7381-D501**
1996, Tacoma	7548-D433**	D/N	1358-505*
1996, Tacoma 4WD	7549-D436**	D/N	1397-589*
1996, Land Cruiser	7298-D502**	D/N	1383-549*
	OR	/D	7487-D606**
1996, 4 Runner	7298-D611**	D/N	1397-589*
1996, RAV-4	7441-D695**	D/N	1385-587*
	(Note #10)		
1996, T100 1Ton	7486-D605**	D/N	1383-549*

VOLKSWAGEN (See Comments)

1996, Cabriolet	7570-D696**	D/N	1450-S662
	(Notes #2 & #11)		
	OR	/D	7234-D340**
1995, Cabriolet	7570-D696**	D/	
1996, Golf	7569-D694**	D/N	1450-S662
	(Notes #1 & #9)		
	OR 7570-D696**	D/D	7234-D340**
1996, Golf GTI	7434-D687**	D/D	7234-D340**
1995-93, Golf	7570-D696**	D/	
1995-94, Golf GTI	7572-D684**	D/	
	(Note #4 & #8)		
1993, Golf GTI	7570-D696**	D/	
1995-89 (Late), Corrado	7571-D684**	D/	
	(Note #3 & #8)		
1996, Jetta	7569-D694**	D/N	1450-S662
	OR 7570-D696**	D/D	7234-D340**
	OR 7434-D687**	D/	
1995-93, Jetta	7570-D696**	D/	
	OR 7572-D684**	D/	
1996, Passat	7570-D696**	D/N	1355-S712
			(Note #12)
	OR 7571-D684**	D/D	7234-D340**
	OR 7434-D687**	D/	
1995, Passat	7571-D684**	D/N	1355-S712
	OR 7570-D696**	D/	
1994-92, Passat	7571-D684**	D/	
	OR 7570-D696**	D/	
1991-90, Passat	7570-D696**	D/	

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
1355	1355-S712	1996-95 Volkswagen Passat Rear
7441	7441-D695	1996 Toyota RAV-4 Front

Shoe with Several Linings:

<u>Shoe</u>	<u>Assembly</u>	<u>Assembly</u>
D684	7571-D684	7572-D684

C O R R E C T I O N S

We have been advised that a number of Volkswagen (front disc) applications going back as far as late 1989 have changed due to a design change in the shoe and lining which went undetected until now. The start date for different applications varies. The part numbers affected are:

7177-D227	7570-D696
7143-D227	7571-D684
7143-D290	7572-D684

Consult individual model (Cabriolet, Corrado, Golf, Golf GTI, Jetta and Passat) for specific dates.

Bulletin #3-951 incorrectly lists Nissan Maxima rear as 7533-D640. The correct listing is 7533-D540.

Bulletin #3-951 incorrectly lists Nissan Quest front as 7546-D576. The correct listing is 7456-D576.

Bulletin #1-951 listed Chrysler Mini-Vans (Caravan, Voyager, T&C) rear brake as FMSI 1485-S703. The correct listing is FMSI 1485TT-S703. FMSI segment 1485 has been cancelled and replaced by 1485TT.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7569</u>	7569-D694
	45.2 x 18.7 x 93.7	2 IM
	45.2 x 18.9 x 120.6	2 IM
	(1.78 x .736 x 3.69)	
	(1.78 x .745 x 4.75)	
Note #2	<u>FMSI 7570</u>	7570-D696
	47.0 x 15.2 x 107.0	4 IM
	(1.86 x .600 x 4.21)	
Note #3	<u>FMSI 7571</u>	7571-D684
	47.0 x 18.6 x 107.0	4 IM
	(1.86 x .732 x 4.21)	
Note #4	<u>FMSI 7572</u>	7572-D684
	47.0 x 18.6 x 107.0	4 IM
	(1.86 x .732 x 4.21)	

Note #5	<u>FMSI 1485TT</u> 250.0dd - 55.0 x 6.1 x 261.9 (9.84 - 2.17 x .240 x 10.31)	1485TT-S703 4 - 40
Note #6	<u>FMSI 1485ATT</u> 250.0dd - 55.0 x 6.1 x 261.9 (9.84 - 2.17 x .240 x 10.31)	1485ATT-S714 4 - 48
Note #7	<u>FMSI 1494</u> 279.4dd - 55.4 x 4.7 x 221.0 (11.00 - 2.18 x .185 x 8.70)	1494-S713 4 Bonded

DISC BRAKE SHOE ASSIGNMENTS

Note #8	<u>FMS D684</u> 119.5 x 5.1 (4.70 x .201)	7571-D684 7572-D684	Volkswagen
Note #9	<u>FMS D694</u> 141.5 x 5.2 141.5 x 5.1 (5.57 x .205) (5.57 x .201)	7569-D694	Volkswagen
Note #10	<u>FMS D695</u> 133.1 x 5.6 (5.24 x .220)	7441-D695	Toyota
Note #11	<u>FMS D696</u> 119.5 x 5.1 (4.70 x .201)	7570-D696	Volkswagen

DRUM BRAKE SHOE ASSIGNMENTS

Note #12	<u>FMS S712</u> 230.0 x 38.5 (9.06 x 1.52)	1355-S712	Volkswagen
Note #13	<u>FMS S713</u> 279.5 x 55.4 (11.00 x 2.18)	1494-S713	Land Rover
Note #14	<u>FMS S714</u> 250.0 x 55.0 (9.84 x 2.17)	1485ATT-S714	Chrysler Dodge Plymouth

CLUTCH FACING APPLICATIONS BY MODEL

DODGE

1989, Colt

8071
(Note #20)

DODGE TRUCK

1993-92, Truck

10032
(Note #26)

CLUTCH FACING APPLICATIONS BY MODEL (con't)FORD

Ranger 8072
(Note #21)
1992-90, Probe 9063
(Note #23)

GEO

Metro 661
(Note #15)
1993-92, Storm 736J
(Note #16)

HONDA

1990-88, Accord 8037D
(Note #18)

MAZDA

1991-88, 626/MX6 9063

NISSAN

1989-87, Pathfinder 8070
(Note #19)
1992-81, Sentra 8070
1995-82, Maxima 9065
(Note #25)

PLYMOUTH

1989, Colt 8071

TOYOTA

1994-80, Tercel 785C
(Note #17)
Toyota 9062
(Note #22)

CLUTCH FACING ASSIGNMENTS

Note #15	<u>FMSI 661</u>						
	6.69	x	4.33	x	.118	12 Gr A Str	- 12
Note #16	<u>FMSI 736J</u>						
	7.87	x	5.12	x	.128	16 Gr A Str	- 16
Note #17	<u>FMSI 785C</u>						
	7.50	x	5.20	x	.138	16 Gr A Str	- 16
Note #18	<u>FMSI 8037D</u>						
	8.86	x	5.91	x	.138	16 Gr A Str	- 16
Note #19	<u>FMSI 8070</u>						
	8.64	x	5.51	x	.138	16 Gr A Str	- 16

CLUTCH FACING ASSIGNMENTS (con't)

Note #20	<u>FMSI 8071</u>						
	8.46	x	5.54	x	.140	16 Gr A Str	- 16
Note #21	<u>FMSI 8072</u>						
	8.83	x	5.95	x	.152	16 Gr A Str	- 16
Note #22	<u>FMSI 9062</u>						
	9.29	x	5.96	x	.137	32 DGAP	- 32
Note #23	<u>FMSI 9063</u>						
	9.43	x	6.33	x	.138	16 Gr A Str	- 16
Note #24	<u>FMSI 9064</u>						
	9.84	x	6.30	x	.150	32 DGAP	- 32
Note #25	<u>FMSI 9065</u>						
	9.44	x	6.31	x	.140	36 DGAP	- 36
Note #26	<u>FMSI 10032</u>						
	10.99	x	6.50	x	.130	40 DGAP	- 40

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.