Engineering

CHEMICAL AND ENVIRONMENTAL SERVICES UNIT

INDUSTRIAL HYGIENE ANALYSIS REPORT EXTENSION SHEET

ANALYSIS NO.	CUSTOMER	ADDRESS
890185	Genuine Parts Co., Inc.	Raylock, Hancock, MD

SAMPLE NUMBER	LOCATION (or employee)	TEST RESULTS	TIME-WEIGHTED AVERAGE	HYGIENIC STANDARD
426F	Darrel Miller-clutch disc driller	Total Fibers Present*		
425F	Darrel Miller-clutch disc driller	Total Fibers 0.422 fibers/cc		
224F	Darrel Miller-clutch disc driller	Total Fibers Present*		
427F	David Golden-burn room operator	Total Fibers Present*		
429F	David Golden-burn room operator	Total Fibers 0.304 fibers/cc		
217F	David Golden-burn room operator	Total Fibers Present*		
436F	Allen Wigfield-disc brake riveter	Total Fibers 0.125 fibers/cc		
430F	Allen Wigfield-disc brake riveter	Total Fibers 0.454 fibers/cc		
223F	Allen Wigfield-disc brake riveter	Total Fibers 0.370 fibers/cc		

SPECIAL NOTES

C-15449-1 PRINTED IN U.S.A.
R901

TRAVELERS INSURANCE COMPANIES
HARTFORD, CONNECTICUT

NOVO20301