MAREMONT
CORPORATION

INTER-OFFICE CORRESPONDENCE

RECEIVED
SEP 17 1980
LAW DEPT.

TO R. C. Rogers

FROM: W. C. Burkhead

DATE: September 16, 1980

SUBJECT: OSHA ASBESTOS WARNINGS ON SEARS BRAKE LINING PACKAGING

RECEIVED
OCT 21 1980
LAW DEPT.

PLAINTIFF'S EXHIBIT
MAR-328

Please find attached the latest recommendation from Sears Legal Department that the warning labeling isn't required.

There is an action step outlined in the second paragraph of Mr. Barnett's memo that should be completed as soon as possible. Let me know if you need any assistance from Maremont to complete the requirement.

CB.
WCB/dk

att.

cc: W. N. Bockay
J. H. Sherr

Bill,
I would like this issue closed by 10/24/80.
CB 10/24/80
cc: J. Sherr

11 54

MAR 001412

*Call R.C. Rogers on Thursday.

TI 55

CAUTION - ASBESTOS DUST HAZARD

Contains Asbestos Fibers

Avoid Creating Dust

Breathing Asbestos Dust May Cause Serious Bodily Harm

-o0o-

Dust hazards may exist if mishandled when installing, removing, or machining. Use safe techniques and approved equipment. For further information, contact P.O. Box 737, Antioch, TN 37013

MAR 001413

CAUTION - ASBESTOS DUST HAZARD

Contains Asbestos Fibers

Avoid Creating Dust

Breathing Asbestos Dust May Cause Serious Bodily Harm

-•0•-

Dust hazards may exist if mishandled when installing, removing, or machining. Use safe techniques and approved equipment. For further information, contact P.O. Box 737, Antioch, TN 37013

TI 56

MAR 001414