TB 442

D4.TXT 6,434

DATE:
REVISED DATE:07/23/86

MIXING PULP [redacted] LONG FIBER AND 7M SHORT FIBER

JOB TYPE:
ROUTINE

PERMITS REQUIRED:
NONE

POTENTIAL HAZAROS:
FALLS,PINCH POINTS, SLIPPERY SURFACE, BODY POSITIONS AND ASBESTOES

[redacted]:
[redacted] BE AWARE OF TRIPPING HAZARDS; [redacted] POINTS- HANDLING SACKS AND OPERATING VALVES; [redacted] WET FLOOR AND ASBESTOES; [redacted] HANDLING ASBESTOES SACKS; [redacted] DUST HAZARD- AVOID BREATHING DUST; WEAR ASSIGNED PROTECTIVE EQUIPMENT, DO NOT REMAIN IN AREA UNLESS YOUR WORK REQUIRES IT. BREATHING ASBESTOES [redacted] HAZARDOUS TO YOUR HEALTH.

15

SAFETY [redacted]
HARD HAT, RESPIRATOR, SIDESHIELD GLASSES, ~~HEARING PROTECTION~~, MONOGOGGLES, CHEMICAL GLOVES, WHITE SUIT, ~~DUST MASK~~, AND RUBBER BOOTS.

CONFO WITH APPROVED F. TERS OR FORCED AIR RESPIRATOR

SPECIAL TOOLS:
NONE

REFERENCES:
NONE

OTHERS:
ASBESTOS [redacted] LOCATED IN THE HAZARD COMMUNCATION MANUAL.

JOB PROCEDURE BY STEPS:
RED TAG AND LOCK OUT PROCEDURES
MIXING PULP 3F-700 LONG FIBER AND 7M SHORT FIBER

TO RED TAG P-518A:
1. CLOSE SUCTION VALVE AND TAG.

PLAINTIFF'S EXHIBIT
DOW-886

STO1175772