



INTERNAL CORRESPONDENCE

UNION CARBIDE CORPORATION
Linde Division
Western Region

JUL 14 1977

WFS V. RIF. TEL. FR. CEC. GJK.
PITTSBURGH, CALIFORNIA 8-1559

LINDE DIVISION

LOVERIDGE ROAD AND CALIFORNIA AVENUE, P. O. BOX 1547

To (Name) Mr. L. L. Vroman
Division One California
Location San Francisco, CA. 94111

Date July 13, 1977
Originating Dept. Pittsburg Plant 80-935

Answering letter date

Copy to

Subject Carcinogen Registration Form and
Handling of Carcinogens Cal-OSHA

Code: 1.665

Dear Mr. Vroman:

Attached is a Carcinogen Registration Form that must be sent in to the Industrial Safety Division of Cal-OSHA. Please review and comment.

The only carcinogen that most Linde plants are exposed to is asbestos.

Title 8, Section 5208, Section C would apply for those locations that use hot piping insulation containing asbestos fibers. Section C, Work Practices, says in general that this material must be handled wet.

Mr. F. Humphreys, Jr. of the Cal-OSHA Concord office stated that if such insulation on piping is exposed with outer protective cover off or torn, that area must be repaired while wet, or must be kept wet until repaired.

Also, asbestos scrap must be collected wet and disposed in sealed impermeable (plastic) bags or containers. Further disposal must be in a Class A dump site.

This also brings up the asbestos content of Durabla gasket materials and the questions of handling per OSHA and Cal-OSHA.

Yours very truly,

[Signature]
Supt. - Production

O.L. LOOMIS:aw
Attach.

410455

UCC 009959

PLAINTIFF'S EXHIBIT

UC-4193

