PLAINTIFF'S EXHIBIT

UC-5229

Friday, February 8, 1963

39th day – 326 days follow

WENT STRAIGHT TO S. CHARLESTON @ 7:30 TO COUNT DUST

(1) COUNTED ALL SAMPLES RECEIVED ON THURSDAY

(2) CALLED DON MATHENY & SET UP NEW DUST SURVEY FOR WEEK of 2-18-63 TO CHECK KAYLE THEN THERMODESIC LATER

(3) TALKED TO HERB KAUFMAN

LEFT @ 6:00 & WENT TO INSTITUTE TO PICK UP DATA FOR DUST EVAL.

File X-9
10-7-81 MCJ

P-10
9-9-81
L.G.A.

Peak X-10
10-7-81 MC

P-10

Tuesday, March 12, 1963

71st day – 294 days follow

Arr 7:30 Ply

1) Called Tom Higgins for Cost Info on Aqueous Waste Incinerator but got no answer.
(2) Called Golden Hutton for Cost Info. on Fence Maintenance but got no answer
3) Talked to Ketcham about rejection on AIHA Request.
(4) Went to Tech Center @ 9:00 for meeting with Bob Harper, Art Oberton, & Ed Hodges on S. Charleston Waste Disposal Dump Problem. Finished meeting @ 12:00 & ate @ Cafeteria. Then met with Newt – filled him in on meeting & discussed AIHA rejection.
5) Returned to Plant & met with Ed Slover to obtain info. on gross poundage of waste disposal material – also sent copy of form for info to Doug Bess
(6) Discussed visit to Chuck on Bird Problem with Dave Steinmetz – to go tomorrow
(7) Saw Homer Coombs about vapor problems @ D.O.P. & questioned him about possible substitution of different type of filters.
3) Talked to Herb Kaufman about results of dust check with thermometer

Wednesday, March 13, 1985 Page X-11

72nd day – 293 days follow

Apr 7:45 Pty. Very Foggy 10-7-81 MC

(1) Took Phillip Carey letter to Hazel for typing
(2) Visited Clockhouse with Dave Steinmetz to check out starling tape set up
(3) Called Golden Hutton & asked for cost figures on operational expenses @ the Teepee
(4) Called Tom Higgins & got info on cost etc for aqueous waste incinerator
(5) Talked to Jim Nichols about TDI & Phosgene problems @ New TDI unit
(6) Talked to Billy Allen about meeting either Thursday or Friday morning about noise & degreasers
(7) Talked to Jack Young about phthalic acid burn then contacted Ed Wall & arranged a meeting for Monday
(8) Talked to Herb Kaufman about [illegible]
(9) Got platinum info from Dr Sexton & sent to Nent for method evaluation
(10) Visited lab. saw Fowler about HOL & Chr & Peterson about blacksmith shop problem
(11) Picked up light meter from Polco
(12) Discussed dust problem with Frank Comerford
(13) Worked on Air Poll. Info
(14) " " Dust Report
(15) Checked out starling tape with Steinmetz left @ 7:00

Tuesday, April 30, 1980

120th day – 245 days follow

Last Day for employers to file quarterly Social Security Tax Return and Wage Report, covering three previous calendar months

Page X-13
10-7-81 MC

(1) Talked to Bob Ruckle about Tank 1087 & agreed to run check for benzene & Cr
(2) Ran check @ Tank 1087 – then went to Fiber T. where ran rad. survey on 4 some sources
(3) Checked mail
(4) Talked to Don Pearson about Kaiser letter.
(1). Went to Maint. Instrument Shop where ran rad check on another sealed source & talked to Tom Wilkerson about work procedures in shop
(5) Called Ruckle about Tank 1087 results wanted it repeated tomorrow
(6) Went to lab to see for but not in
(7) " " Cellosize to check two rad sources but had to stop due to pain
(8) Saw Dr. Sexton & met Bob Estep of Owens Corning — talked to Estep about dust analysis & sampling techniques & agreed to provide outline of techniques & to talk to Rosenberg also about [illegible]
(9) Talked to Charlie Crawford about Kaiser letter and desire to check work conditions
(10) Talked to Brad about committee progress & trip to AIHA.
(11) Straighten out A.P. file
(12) Talked to Dr. [illegible] about V.P. Whitson



worked on MAINT INSTRUMENT SHOP LIGHTING Problem.

Wednesday, May 1, 1963

121st day – 244 days follow

Phil X-13
10 7-81 MC

ZL 7:30 TRY

LKED TO BOB RUCKLE ABOUT CHECK OF TANK 1087

CKED TWO RAD SOURCES @ CELLESIZE

LED TO SLOVER WHO COULD NOT MEET UNTIL 1100

LLED GEO FOX & ARRANGED MEETING FOR 12:00

GUY ARBAUGH ABOUT SYRINGE SAMPLE IN HIS OFFICE

LKED TO BOB ESTER of OWENS CORNING & SET UP MEETING

HE & W.A. LOTZ FOR: MAY 16TH @ 10:00

LLED KETCHAM & DISCUSSED SEALED SOURCES, A.I.H.A. MEETING

ALLED TOM WILKINSON FOR INFO. ON TYPE of WORK IN

RUMENT SHOP AREAS.

TALKED TO BILL MOLLAHAN ABOUT CONTINUOUS SAMPLED FOR

N

ALLED DICK REPAIRE FOR INFO. ON HCN MONITOR

LKED TO JOHN PERKINS ABOUT DOWN TIME ON GAS. CYPER.

SUGGESTED I CONTACT PAUL LAINE - LAINE NOT IN.

TALKED TO DR SEXTON ABOUT CHECKING SIMPLIFIED

ORT FORMS.

LET WITH GEO FOX & DISCUSSED HCl SAMPLING, LAB REQUEST

MEETING WITH T.C. WHITSON

TALKED TO CARL BEARD ABOUT COMM. PROPOSALS FOR FUTURE

POINIER & ARRANGED FOR HIM TO MEET T.C.

TSON WHEN HE ARRIVES.

ALLED LND TO RELATE ABOUT WHITSON BUT HE DIDN'T LA

T WITH ED SLOVER & SET UP TO CHECK ON POSITION

File X-14

Thursday, May 16, 1963 10-7-81 MGE

136th day – 229 days follow

ARR 7:30 TRC

(1) CALLED MARGE ENSMINGER FOR INFO ABOUT ALKYL BENZENE UNIT & COAL PLT RESEARCH

(2) CONTACTED ED SLOVER ABOUT RESIDUES @ NEW ALKYL BENZENE UNIT

(3) TALKED TO JERRI ABOUT RUNNING COPIES OF TDI DATA

(4) " " DOUG BESS ABOUT BEARDS VISIT FRIDAY

(5) " " POINIER ABOUT HCl CHECK @ LEACHING PT & I.R. ALKYL BENZENE CHECK

(6) CALLED FLEETWOOD FOR INFO ON NEW ALKYL BENZENE WASTE STREAM

(7) TALKED TO FRED WILLIAMS ABOUT LOAN OF SOUNDSCOPE

(8) " " WALTON ABOUT GENERAL SAVINGS PLAN

(9) MET WITH WILLIAM TOTZ & BOB [illegible] OF OWENS CORNING CO & DISCUSSED DUST TECHNIQUE FOR AIR ANALYSIS

(10) TALKED TO FOWLER ABOUT LOAN OF EQUIPMENT

(11) CHECKED WITH HAZEL ABOUT RESIDUE LIST & GAVE HER HQ REPORT & RAD REPORTS PLUS TDI DATA TO COPY

(12) CHECKED WITH DOUG BESS & [illegible] ABOUT STATE GOV. VISIT [illegible]

(13) TALKED TO IND ABOUT [illegible]

[illegible]