

FILE NAME: WR Grace (WRG)

DATE: November 18, 1960

DOC#: WRG272

DOCUMENT DESCRIPTION: 1960 Letter from OP Stewart to LL Marchall regarding trouble with blinding on the stoner decks.

November 13, 1960

Mr. L. L. Marshall

Ellwood City

Mr. O. F. Stewart

Travelers Rest

Dear Lloyd:

John Huxley in California has written and stated that they are having a lot of trouble with blinding on the stoner decks. The blinding is caused by small particles of asbestos becoming lodged in the holes on the stoner deck. He uses Libby #3 and #4.

Since you use Libby #3 and #4 I was wondering if you have this trouble and if so, what do you do about it?

Would you tell me your experience with the stoner at Ellwood.

Best personal regards!

Very truly yours,

O. F. Stewart

OPS:es