PLAINTIFF'S EXHIBIT

SH-1757

MEETING NOTICE

AUGUST 31,1988

SUBJECT: DU-2 Instrumentation Cable Tray Fireproofing

DAY/DATE/TIME: Wednesday/August 31,1988/10:00 am

TARGETED DURATION: 1 hour

PLACE: FOB Conference Room 149

PURPOSE: Determine if all asbestos fireproofing material should be removed and replaced.

SUGGESTED ATTENDANCE:

R.L. Jacoby - FOB
W.L Harbuck - FOB
D.E. Grace - WZS
D.H. Mai - FOB
B.K. Kruelskie - FOB
G. Vasquez - FOB
W.E.J. Schrof - FOB

INFORMATION COPIES:

P.J. Chan - FOB
D.G. Jaeger - FOB
P.K. Cole - FOB

W.E.J. Schrof

LAM 018203

Saved under: ASBMEMO

AGENDA

1. Summarize the memo

   (a) Location of the cable tray

   (b) Location of the damaged sheets

2. Emergency shutdown instrumentation found in the cable trays.

   Tray C

   Flow control instrumentation for straight run residue to South and North Vacuum Flasher.

South	North
FC-451 to FC-454	FC-461 to FC-464
FIC-1004/FIC-1005	FIC-1006/FIC-1007

   LV-1170 (Vacuum Flasher Level to Shutdown VFLD pumps 5182 & P5183)

   FT-256 Reflux Secondary Accumulator Flow

   FX-537 Flasher Accumulation Vent Gas to 1psi system

   FT-1146 ORCTG

   Tray B

   FT-451 to FT-454
   FT-461 to FT-464 Inputs to low flow emergency alarms
   FT-1006/FT-1007

LAM 018204