Monsanto

CALL REPORT—ORGANIC DIVISION

DICTATE IN SEQUENCE:
1. HEADING INFORMATION
2. NAMES OF ADDRESSEES
3. NAMES OF CARBONEES
4. IMMEDIATE ACTION NEEDED
5. REPORT ON CALL

REPORT CAPTIONS:
1. OBJECTIVE
2. PERSONS CONTACTED
3. RESULTS
4. ACTION REQUIRED

CUSTOMER NAME					DATE OF CALL
RADIATOR SPECIALTY CO					6/13/72
CITY AND STATE			DATE RECEIVED		DATE TYPED
CHARLOTTE, N.C.			6/21/72		6/21/72
CUSTOMER MAILING LIST CHANGES—SERVICE CENTER USE ONLY					
NAME AND TITLE	PUT ON	ARE OFF	MP	MAG	CATEGORY CODES
REGION	SERVICE CENTER	SALESMAN			
SOUTHERN	ATLANTA	M. L. MARCUM pr			

TO CUMMING PATON - ST. LOUIS CC J. H. DAVIDSON - ST. LOUIS

CONTACT: George Kologiski - Research

OBJECTIVE: To determine the results of the evaluation of MCS fluid to replace Aroclors at this account.

RESULTS: George has completed an evaluation of the samples of MCS 1040, 1249 and 1266 as automatic transmission lubricants and seal swellers. His interest in color and viscosity indicated that MCS 1249 seemed to be the best replacement for the Aroclors. However, he requested information on load bearing capabilities and Failex information for extreme pressure lubrication with the MCS fluids. He also requested suggestions on which one of the fluids was most effective in desolving and removing sludge deposits.

George asked for any information which we may have on medical counter measures for Aroclor consumption. It seems that a Doctor called last month from Boston and a 19 year old drunk kid had consumed a can of automatic transmission fluid containing the Aroclors. They heard nothing else from the Doctor in Boston, but did request these counter measures on the Aroclors as well as on the new MCS products which we have delivered for evaluation.

NOTE: J. H. DAVIDSON - Do we have load bearing information and Failex information for the MCS fluids as well as medical counter measures for the Aroclor and MCS fluids?

George has not evaluated any other products other than the MCS fluids which we have sent him and he feels that at present he may find a suitable replacement for the Aroclors from one of these.

Mickey Marcum

S-331 (REV. 12/68)

3 – SERVICE CENTER COPY

MONS 072268